



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2004777
INV Date 07/07/2020
Reference CC6/QBE20003912/Uea3q2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. GBG 3964M
Insured Veh. GBD 8515J
Claim No. VC013558
Policy No. 8-V0021299-MVA-R001
Accident Date 09/03/2020
Inspection Date 12/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE20003912/Uea3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 07-07-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8515J	Veh. Inspected	GBG 3964M
Policy No.	8-V0021299-MVA-R001	Coverage (\$)	0.00
Claim No.	VC013558	Excess (\$)	0.00
Assign From		Assign Date	12/03/2020

2. Vehicle Particulars & Condition

Make & Model	FIAT DOBLO CARGO (M)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZFA26300000006G87520	Colour	WHITE
Odometer	102128	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	195/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/03/2020	Inspection Date	12/03/2020
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3964M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	745.00	734.34
1	SET REAR BUMPER CLIPS	NECESSARY	65.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	752.00	520.92
1	REAR BUMPER BRACKET	NOT NECESSARY	155.00	-
1	REAR BUMPER REFLECTOR	SERVICEABLE	117.60	-
2	REAR TAIL LAMP @\$462.70	N/S CRACKED	925.40	420.50
1	REAR FLOOR PANEL GARNISH	NOT NECESSARY	1,379.80	-
1	REAR LH TAILGATE	BADLY DENTED	2,395.00	2,355.50
1	REAR LH TAILGATE GLASS	SHATTERED	841.50	841.50
1	REAR LH TAILGATE WEATHERSTRIP	NOT NECESSARY	344.50	-
1	REAR LH TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	384.90	384.90
1	SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	164.50	-
1	REAR LH TAILGATE WIPER MOTOR	CRACKED / JAMMED	428.00	428.00
1	REAR LH TAILGATE WIPER ARM	BENT	165.30	165.30
1	REAR LH TAILGATE WIPER RUBBER	NOT NECESSARY	98.00	-
2	REAR LH TAILGATE HINGE @\$166.30	BENT (1 PCS ONLY)	332.60	166.30
1	REAR LH TAILGATE LOCK	DENTED / JAMMED	331.00	331.00
1	REAR LH TAILGATE OUTER GARNISH	CRACKED	279.00	279.00
1	REAR LH TAILGATE 'DOBLO' EMBLEM	NECESSARY	118.00	80.20
1	TAILGATE 'MEXI' EMBLEM	NECESSARY	86.00	62.50
2	REAR LH TAILGATE NUMBER PLATE LAMP @\$51.50	NOT NECESSARY	103.00	-
1	REAR LH TAILGATE NUMBER PLATE OUTER GARNISH	NO SUCH PARTS	154.40	-
1	REAR LH TAIL LAMP PANEL	TO REPAIR SEE LABOUR	989.30	-
1	REAR RH TAILGATE	DENTED / BENT	1,895.90	1,844.71
1	REAR RH TAILGATE WEATHERSTRIP	NOT NECESSARY	297.00	-
1	REAR RH TAILGATE LOCK TOP	NOT NECESSARY	189.30	-
1	REAR RH TAILGATE LOCK UPPER	NOT NECESSARY	192.90	-
1	REAR RH TAILGATE OUTER GARNISH	GRAZED	321.80	186.45
1	REAR RH TAILGATE 'PROFESSIONAL' EMBLEM	NECESSARY	163.50	163.50

Report Ref No. CC6/QBE20003912/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH TAILGATE 'FIAT LOGO' EMBLEM	NOT NECESSARY	87.80	-
1	REAR RH TAILGATE GLASS	NOT NECESSARY	680.00	-
	LESS 10% DISCOUNT		-	-901.46
			15,183.00	8,113.16
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REAR LH TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR LH TAILGATE '70KM/H' STICKER (SN)	NECESSARY	15.00	10.00
1	REAR LH TAILGATE NUMBER PLATE AND BASE (SN)	BENT	48.00	40.00
1	REAR RH TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR RH TAILGATE GLASS SEALANT (SN)	REPEATED	80.00	-
1	REAR RH TAILGATE '6PAX' STICKER (SN)	NECESSARY	15.00	10.00
			538.00	340.00
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETC.S.INCLUSIVE OF THE REPAIR OF REAR LH TAIL LAMP PANEL .INCLUSIVE OF THE REPAIR OF REAR LH TAIL LAMP PANEL .		1,000.00	450.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AF.		1,000.00	800.00
	REMOVE & REINSTALL REAR RH & LH WINDSCREEN GLASS TO FACILITATE REPA.		240.00	200.00
	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHAN.		180.00	100.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	30.00
	REMOVE AND REFIX REAR REVERSE SENSOR .		100.00	50.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT ARE.		80.00	60.00
			-	-
			-	-
			-	-
			2,680.00	1,690.00
GRAND TOTAL			18,401.00	10,143.16



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,100.00
---	--	--	-----------------

Report Ref No. CC6/QBE20003912/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. GBG 3964M

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 3964M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 3964M

RE-INSPECTION

