

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG20003915/ATD3E2**Date:** 29/10/2020REFERENCE

Insured/Claimant:	JANG HYE YOUNG	Policy No:	1900131025
Date of Loss:	07/03/2020	Nature of Claim:	OD
		Claim No:	0498099234SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN2690S	Engine No:	DAX056916
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZF9K2107762
Reg. Date:	30/07/2019 (Man. Year: 2019)	Odometer:	6126 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,415.00	1,402.60	18,012.40	92.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,072.00	2,372.00	2,700.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,487.00	3,774.60	20,712.40	84.59
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	23,487.00	2,774.60	20,712.40	88.19
+ GST 7.00/7.00% (S\$)	1,644.09	194.22	1,449.87	88.19
Nett Amount (S\$)	25,131.09	2,968.82	22,162.27	88.19

INSPECTION

Date of Assignment:	12/03/2020		
Date Inspected:	12/03/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,445.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	254.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - RH	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	105.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	134.00 FS	*- FS
6	1		*FRONT BUMPER FRONT SPOILER	Repair	709.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	447.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	161.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	3,327.00 FS	*- FS
10	1		*QUATTRO INSCRIPTION	Not Necessary	90.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	230.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	537.00 FS	*429.60 FS
13	1		*FRONT BUMPER END CAP - RH	Not Necessary	86.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	857.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	269.00 FS	*- FS
16	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
17	1		*HORN - RH HIGH TONE	Not Necessary	184.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
19	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
20	1		*HEADLIGHT MOUNTING - RH	Not Necessary	112.00 FS	*- FS
21	1		*LED HEADLIGHT - RH	Not Necessary	7,462.00 FS	*- FS
22	1		*LIFT CYLINDER - RH	Not Necessary	132.00 FS	*- FS
23	1		*WHEEL SPOILER - RH	Not Necessary	146.00 FS	*- FS
24	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,190.00 FS	*952.00 FS
25	1		*RADIATOR AIR GUIDE - RH	Not Necessary	53.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE - CENTRE	Not Necessary	40.00 FS	*- FS
27	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
28	1		*SUNDRIES	Necessary	300.00 FS	*21.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 19,415.00 1,402.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTAL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	2,800.00	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	5,072.00
				2,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >