



Case Details

Case Reference Number : TAX/03/20/2028
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF330X

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-10803-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 10/03/2020 06:00 AM
 Vehicle Age(In Months) : 27

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair	XR
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	/ PD
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67 \$39.68	Replace	/ Nec
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xsvc
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	Xsvc
Total Spare Part Cost									8,722.36	Surveyor Total				799.50
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0
Final Spare Part Cost									8,722.36	Final Sur Total				799.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair	X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ Nec
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	X SVC
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	82.10	25.00	61.57	Replace	0	0	Not Give	X SVC
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Not Give	X SVC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									8,722.36		Surveyor Total 799.50			
Lump Sum Discount (%)									0.00		Lump Sum Dis (%) 0			
Final Spare Part Cost									8,722.36		Final Sur Total 799.50			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
Total:			1,674.00	650.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
5	Main	TO RESPRAY VIEW MIRROR	180.00	0	
6	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
Total:			1,674.00	650.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	20	Balancing only
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			780.00	40.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,722.36	799.50
Total Labour Cost	845.00	300.00
Total Spray Painting	1,674.00	650.00
Other	780.00	40.00
Overall Total	12,021.36	1,789.50
Lump Sum Repair Option		
Lump Sum Total	0.00	1,789.50
Surveyor Approved Amount		1,789.50
No of Repair Days*	6	3
Remarks		P/P Repair, Before paint photo. Tyre balancing only.
Surveyor Name		Sun Pin (LKK)

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

11/03/2020

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: