

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20003919/NTD3E2

**Date:** 17/08/2020

### REFERENCE

Insured/Claimant: RODNEY LEONG @JOKUMI

Policy No: 1900084777

Date of Loss: 04/02/2020

Nature of Claim: OD

Claim No: 4009252041SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ8060Y**

Make & Model: HONDA NM4-02 A, 745cc

Engine No: RC70E2100848

Reg. Date: 11/10/2014 (Man. Year: 2014)

Chassis No: RC821000818

Colour: Multi-colour

Odometer: 4235 km

Engine Capacity: 745 cc

Market Value/New Car Price: S\$13,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R18

Rear Tyre Size: 200/55 R17

Front Left Side: Timsun 4 mm

Rear Left Side: Bridgestone 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,780.70	11,121.60	4,659.10	29.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,150.00	1,940.00	62.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,870.70</b>	<b>12,271.60</b>	<b>6,599.10</b>	<b>34.97</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>9,500.00</b>		
<b>- Excess (\$\$)</b>	750.00	750.00	0.00	0.00
<b>(\$\$)</b>	18,120.70	8,750.00	9,370.70	51.71
<b>+ GST 7.00/7.00% (\$\$)</b>	1,268.45	612.50	655.95	51.71
<b>Nett Amount (\$\$)</b>	<b>19,389.15</b>	<b>9,362.50</b>	<b>10,026.65</b>	<b>51.71</b>

### INSPECTION

Date of Assignment: 12/03/2020

Date Inspected: 12/03/2020 Inspected At:

Bike Production Pte Ltd (HQ)

610 SERANGOON ROAD

Singapore 218216

Estimated Period of Repair: 4.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Scratched	495.00 FL	*495.00 FL
2	1		*BRACKET COMP FRONT FENDER	Bent	165.00 FL	*165.00 FL
3	1		*FRONT WHEEL AXLE	Serviceable	214.00 FL	*- FL
4	1		*FRONT LEFT FORK ASSY	Repair	1,050.00 FL	*- FL
5	1		*FRONT BRAKE DISK	Warped	440.00 FL	*440.00 FL
6	2		*STEERING STEM BEARINGS	Necessary	90.00 FL	*90.00 FL
7	1		*FRONT FORK STEERING STEM	Bent	490.00 FL	*490.00 FL
8	1		*LEFT SIDE MIRROR ASSY	Broken	650.00 FL	*650.00 FL
9	1		*LEFT SIDE FAIRING INNER BRACKET	Bent	245.00 FL	*245.00 FL
10	1		*LEFT SIDE FAIRING ASSY	Cracked	495.00 FL	*495.00 FL
11	1		*LEFT MIDDLE FAIRING GLOSS BLACK	Cracked	345.00 FL	*345.00 FL
12	1		*CENTRE LOWER COVER ASSY	Cracked	345.00 FL	*345.00 FL
13	1		*CENTRE UPPER COVER ASSEMBLY	Cracked	325.00 FL	*325.00 FL
14	1		*STEERING HANDLE	Bent	250.00 FL	*250.00 FL
15	1		*BRAKE LEVER (SCRATCHED)	Not Consistent With The Impact	115.00 FL	*- FL
16	1		*RIGHT HANDLE BALANCER (SCRATCHED)	Not Consistent With The Impact	65.00 FL	*- FL
17	1		*REAR BRAKE PEDAL COMP (SCRATCHED)	Not Consistent With The Impact	245.00 FL	*- FL
18	1		*LEFT FRONT FOOTREST	Deformed	385.00 FL	*385.00 FL
19	1		*LEFT FRONT FOOTREST BRACKET HOLDER	Deformed	375.00 FL	*375.00 FL
20	1		*RIGHT FRONT FOOTREST (SCRATCHED)	Not Consistent With The Impact	385.00 FL	*- FL
21	1		*RIGHT FRONT FOOTREST BRACKET HOLDER (SCRATCHED)	Not Consistent With The Impact	375.00 FL	*- FL
22	1		*LEFT REAR FOOTREST SIDE COVER	Deformed	335.00 FL	*335.00 FL
23	1		*SIDE STAND	Scratched	295.00 FL	*295.00 FL
24	1		*LEFT SIDE CASE ASSEMBLY	Deformed	1,595.00 FL	*1,595.00 FL
25	1		*EXHAUST ASSY (SCRATCHED)	Not Consistent With The Impact	1,750.00 FL	*- FL
26	1		*FRONT SPORT RIM	Repair	880.00 FS	*- FS
27	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
28	1		*LEFT SIDE SKIRTING (GLOSS BLACK)	Cracked	275.00 FL	*275.00 FL
29	1		*LEFT REAR SIGNAL ASSY	Scratched	195.00 FL	*195.00 FL
30	1		*LEFT REAR SIGNAL COVER	Cracked	214.00 FL	*214.00 FL
31	1		*RADIATOR ASSY	Deformed	880.00 FL	*880.00 FL
32	1		*LEFT ALUMINIUM COVER	Deformed	275.00 FL	*275.00 FL
33	1		*ENGINE COVER LEFT	Cracked	245.00 FL	*245.00 FL
34	1		*FRONT LEFT SIGNAL	Cracked	195.00 FL	*195.00 FL
35	1		*FRONT LEFT SIGNAL UPPER COVER	Cracked	190.00 FL	*190.00 FL
36	1		*LEFT BOX SIDE COVER LOWER	Deformed	175.00 FL	*175.00 FL
37	1		*REAR CENTRE COVER	Cracked	235.00 FL	*235.00 FL
38	1		*LEFT UPPER FAIRING	Cracked	485.00 FL	*485.00 FL
39	1		*FRONT LEFT FAIRING	Missing	395.00 FL	*395.00 FL
40	1		*CENTER LEFT FAIRING	Missing	295.00 FL	*295.00 FL
41	1		*HAND BRAKE BRACKET	Bent	235.00 FL	*235.00 FL
42	1		*RIGHT UPPER FAIRING	Cracked	485.00 FL	*485.00 FL
43	1		*COOLANT	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*ERP IU	Cracked	157.00 FS	*157.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (S\$)</b>	<b>17,410.00</b>
					<b>12,331.00</b>	
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>1,629.30</b>
					<b>1,209.40</b>	
					<b>Total Parts (S\$)</b>	<b>15,780.70</b>
					<b>11,121.60</b>	

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING CHARGES	New	150.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	600.00
3	TO REPAIR LEFT FORK	New	300.00	0.00
4	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	150.00	50.00
5	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
6	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	50.00
7	SPRAY PAINT	New	700.00	250.00
8	WELDING	New	150.00	50.00
9	SPORT RIM REPAIR	New	280.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,090.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >