

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20003920/ABS3Q2

**Date:** 15/10/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLL541A **Insured Vehicle No :** SLD5020X

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 3323605627SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLL541A</b>	Engine No:	A2162775GU7X0214
Make & Model:	OPEL MOKKA X, 1.6 CDTI 6AT (LED) (A)	Chassis No:	W0LJD7EC7HB079895
Reg. Date:	13/02/2017 (Man. Year: 2016)	Odometer:	179902 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/55 R18	Rear Tyre Size:	215/55 R18
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,414.40	5,236.30	11,178.10	68.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	2,735.00	4,715.00	63.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>23,864.40</b>	<b>7,971.30</b>	<b>15,893.10</b>	<b>66.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,670.51</b>	<b>557.99</b>	<b>1,112.52</b>	<b>66.60</b>
<b>Nett Amount (S\$)</b>	<b>25,534.91</b>	<b>8,529.29</b>	<b>17,005.62</b>	<b>66.60</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (S\$)</b>		210.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>8,741.29</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,700.00</b>		

#### INSPECTION

Date of Assignment: 11/03/2020

Date Inspected: 11/03/2020 Inspected At: 1st Autoworks Pte Ltd (HQ)  
23 Kaki Bukit Ave 4, #04-01  
Singapore 415933

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,840.00 FL	*- FL
2	10		*REAR TAILGATE INNER TRIM CLIP	Not Necessary	65.00 FL	*- FL
3	1		*LETTERING MOKKA	Necessary	146.00 FL	*146.00 FL
4	1		*LETTERING CDTI	Necessary	110.00 FL	*110.00 FL
5	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	1,258.00 FL	*- FL
6	1		*LHR TAILLAMP	Not Necessary	564.00 FL	*- FL
7	1		*LHR TAILLAMP PANEL	Not Necessary	210.00 FL	*- FL
8	1		*REAR BUMPER UPPER	Distorted	1,800.00 FL	*1,800.00 FL
9	1		*REAR BUMPER LOWER	Distorted	1,390.00 FL	*1,390.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	65.00 FL	*65.00 FL
11	1		*REAR BUMPER TOWING COVER	Not Necessary	90.00 FL	*- FL
12	1		*REAR BUMPER SILL PLATE	Deformed	344.00 FL	*344.00 FL
13	1		*LHF BUMPER REFLECTOR	Cracked	150.00 FL	*150.00 FL
14	4		*REVERSE SENSOR	Damaged (1 PCS ONLY)	880.00 FL	*220.00 FL
15	1		*LHR FENDER	Repair	3,110.00 FL	*- FL
16	1		*LHR FENDER PROTECTOR	Deformed	190.00 FL	*190.00 FL
17	6		*LHR FENDER PROTECTOR CLIPS	Necessary	39.00 FL	*39.00 FL
18	1		*LHR FENDER LINER	Not Necessary	146.00 FL	*- FL
19	3		*LHR FENDER LINER CLIPS	Not Necessary	19.50 FL	*- FL
20	1		*REAR BUMPER AIR VENTILATOR	Cracked	85.00 FL	*85.00 FL
21	1		*LHR BUMPER BRACKET ,GUIDE	Cracked	70.00 FL	*70.00 FL
22	1		*RHR BUMPER BRACKET ,GUIDE	Not Necessary	70.00 FL	*- FL
23	1		*LHR BUMPER BRACKET	Cracked	65.00 FL	*65.00 FL
24	1		*RHR BUMPER BRACKET	Not Necessary	65.00 FL	*- FL
25	1		*REAR BUMPER ABSORBER -LH	Cracked	82.00 FL	*82.00 FL
26	1		*REAR BUMPER ABSORBER -RH	Not Necessary	82.00 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT BAR	Dented	951.00 FL	*951.00 FL
28	1		*REVERSE SENSOR WIRING HARNESS	Not Necessary	325.00 FL	*- FL
29	1		*REAR END PANEL	Repair	1,217.00 FL	*- FL
30	1		*REAR END PANEL TRIM	Not Necessary	220.00 FL	*- FL
31	1		*REAR END PANEL TRIM CLIPS	Not Necessary	45.50 FL	*- FL
32	1		*LHR DOOR	Not Necessary	1,650.00 FL	*- FL
33	1		*LHR DOOR CATCH	Not Necessary	232.00 FL	*- FL
34	1		*LHR DOOR STRIKER	Not Necessary	40.00 FL	*- FL
35	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
36	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
37	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	220.00 FS	*- FS
38	1		*ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>18,176.00</b>	<b>5,807.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,761.60	570.70
<b>Total Parts (\$)</b>	<b>16,414.40</b>	<b>5,236.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,250.00	975.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	3,300.00	1,650.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	65.00	30.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	130.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	130.00	50.00
6	CONDUCT CHASSIS ALIGNMENT OF VEHICLE	New	250.00	0.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	130.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	65.00	0.00
9	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	130.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,735.00</b>
				<b>7,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >