

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20003922/ABS3Q2

**Date:** 03/08/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100446988  
**Claimant**  
**Vehicle No :** SLH9529Z **Insured Vehicle No :** SKZ9983L  
Date of Loss: 03/03/2020 Nature of Claim: TP Claim No: 5717007102SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH9529Z**  
Make & Model: BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A) Engine No: 34369660B37C15A  
Reg. Date: 24/11/2016 (Man. Year: 2016) Chassis No: WBA2B32070V791421  
Colour: Black Odometer: 66099 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,213.00	3,979.55	3,233.45	44.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	780.00	1,420.00	64.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,413.00</b>	<b>4,759.55</b>	<b>4,653.45</b>	<b>49.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
	(S\$) 9,413.00	3,800.00	5,613.00	59.63
<b>+ GST 7.00/7.00% (S\$)</b>	658.91	266.00	392.91	59.63
<b>Nett Amount (S\$)</b>	<b>10,071.91</b>	<b>4,066.00</b>	<b>6,005.91</b>	<b>59.63</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,273.45</b>		

#### INSPECTION

Date of Assignment: 12/03/2020  
Date Inspected: 12/03/2020 Inspected At: New Hock Teck Motor Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, Blk C #01-43  
Autobay@Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 3.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,045.00 F	*1,045.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	80.00 F	*30.00 FL
3	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	225.00 F	*- FL
5	1		*FRONT BUMPER INNER FOAM	Cracked	110.00 F	*110.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	530.00 F	*- FL
7	2		*FRONT BUMPER SENSOR	Not Necessary	536.00 F	*- FL
8	1		*FRONT L/H BUMPER SIDE RETAINER	Not Necessary	28.00 F	*- FL
9	1		*FRONT L/H BUMPER FOG LAMP	Cracked	286.00 F	*286.00 FL
10	1		*FRONT L/H BUMPER FOG LAMP COVER	Deformed	380.00 F	*128.00 FL
11	1		*FRONT L/H GRILLE	Not Necessary	180.00 F	*- FL
12	6		*FRONT L/H GRILLE CLIP	Not Necessary	48.00 F	*- FL
13	1		*FRONT L/H HEAD LAMP	Cracked	2,590.00 F	*2,590.00 FL
14	1		*FRONT L/H HEAD LAMP LOWER BRACKET	Not Necessary	355.00 F	*- FL
15	1		*FRONT L/H FENDER	Not Necessary	580.00 F	*- FL
16	1		*FRONT L/H FENDER COWLING	Not Necessary	190.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,213.00</b>	<b>4,189.00</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$)</b>	0.00	209.45
<b>Total Parts (\$)</b>	<b>7,213.00</b>	<b>3,979.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT FRONT SENSOR	New	120.00	50.00
2	TO CHECK WIRING	New	80.00	30.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	800.00	300.00
5	SPRAY PAINTING	New	800.00	250.00
6	TO DETACH BUMPER SPOILER	New	250.00	150.00
<b>Gross Labour Cost (\$)</b>			<b>2,200.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >