

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003924/UGA3Q2

Date: 11/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M460802
Claimant	Insured Vehicle No :	SKM9651M
Vehicle No : GP9860H		
Date of Loss: 10/05/2019	Nature of Claim:	TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GP9860H	Engine No:	YD25364196A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0004278
Reg. Date:	30/05/2015 (Man. Year: 2014)	Odometer:	138659 km
Colour:	Brown		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,450.20	774.27	3,675.93	82.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	860.00	1,400.00	61.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,710.20	1,634.27	5,075.93	75.64
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	6,710.20	1,300.00	5,410.20	80.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/03/2020	
Date Inspected:	12/03/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2020)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GP9860H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Cut / Torn	850.00 F	*600.50 FN	
2	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	66.80 F	*- FN	
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*35.00 FN	
4	1		*TAILLAMP N/S	Scratched	488.20 F	*224.80 FN	
5	1		*REAR BODY PANEL N/S	Repair	2,995.20 F	*- FN	
					Sub Total (S\$)	4,450.20	860.30
					- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	86.03
					Total Parts (S\$)	4,450.20	774.27

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	40.00
3	TO SPRAY RUST PROOFING	New	50.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	1,000.00	500.00
			Gross Labour Cost (\$\$)	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >