

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003930/FGS3Q2

Date: 09/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLV9429E	Insured Vehicle No :	SHD4422Z
Date of Loss: 19/01/2020	Nature of Claim: TP	Claim No: MCT20010452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9429E	Engine No:	CCZ470803
Make & Model:	VOLKSWAGEN TIGUAN, 2.0 (A)	Chassis No:	WVGZZZ5NZFW053419
Reg. Date:	27/02/2015 (Man. Year: 2014)	Odometer:	81246 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,191.40	534.60	2,656.80	83.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	930.00	470.00	33.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	4,591.40	1,464.60	3,126.80	68.10
Approved Total (Overridden) (\$)		1,100.00		
(\$)	4,591.40	1,100.00	3,491.40	76.04
+ GST 7.00/7.00% (\$)	321.40	77.00	244.40	76.04
Nett Amount (\$)	4,912.80	1,177.00	3,735.80	76.04
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	12/03/2020	
Date Inspected:	23/03/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649
Estimated Period of Repair:	2.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Oct 2020)	
Parts:	N/A	VOLKSWAGEN TIGUAN 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV9429E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHF BUMPER ARCH	Scratched	594.00 FL	*594.00 FL
2	1		*LHF FENDER ARCH	Not Necessary	1,776.00 FL	* - FL
3	1		*LHF FENDER	Repair	1,176.00 FL	* - FL
					Sub Total (S\$)	3,546.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	594.00
						534.60
					Total Parts (S\$)	3,191.40
						534.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	100.00	80.00
2	TO REPAIR FRONT BUMPER ,LH FRONT DOOR AND AFFECTED AREA	New	500.00	400.00
3	TO PUTTY & SPRAY PAINT FRONT BUMPER ,LHF FENDER ,LHF DOOR AAAND AFFECTED AREA	New	800.00	450.00
Gross Labour Cost (\$\$)			1,400.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >