

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003932/T1GS3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M491018
Claimant		
Vehicle No : GBF5171B	Insured Vehicle No :	GBB4212U
Date of Loss: 14/01/2020	Nature of Claim: TP	Claim No: MC20202010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF5171B		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Engine No:	YD25407942A
Reg. Date:	28/11/2016 (Man. Year: 2016)	Chassis No:	JN1MC2E26Z0007322
Colour:	Black	Odometer:	98872 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	LINAM 6 mm	Rear Left Side:	LINAM 6 mm
Front Right Side:	LINAM 6 mm	Rear Right Side:	LINAM 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,158.69	3,520.17	638.52	15.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,640.00	600.00	26.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,398.69	5,160.17	1,238.52	19.36
Approved Total (Overridden) (\$\$)		4,100.00		
(\$\$)	6,398.69	4,100.00	2,298.69	35.92
+ GST 7.00/7.00% (\$\$)	447.91	287.00	160.91	35.92
Nett Amount (\$\$)	6,846.60	4,387.00	2,459.60	35.92
+ Loss of Use (7.0 x S\$60.00/day) (\$\$)		420.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		4,836.00		
Global Sum Settlement (\$\$)		4,800.00		

INSPECTION

Date of Assignment:	12/03/2020		
Date Inspected:	12/03/2020	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 May 2020)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF5171B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	793.80 FL	*793.80 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	57.20 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	206.40 FL	*- FL
5	1		*TAILGATE	Bent	2,338.00 FL	*2,338.00 FL
6	1		*TAILGATE LOCK	Not Necessary	337.50 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Cut	137.50 FL	*137.50 FL
8	1		*TAILLAMP RH/LH	N/S Not Necessary / O/SCracked	525.00 FL	*262.50 FL
9	1		*END PANEL	Bent	581.30 FL	*581.30 FL
10	1		*REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS
11	1		*8 PAX STICKER	Necessary	10.00 FS	*10.00 FS
12	1		*70KM/HR STICKER	Necessary	10.00 FS	*10.00 FS
13	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
14	1		*REAR ADVERTISEMENT STICKER PANEL	Necessary	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,666.70	4,763.10
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,508.01	1,242.93
Total Parts (\$\$)	4,158.69	3,520.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	1,100.00	700.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	700.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
5	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
6	RUST PROOFING	New	50.00	30.00
Gross Labour Cost (\$)			2,240.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >