

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20003934/R1GS3Q2
Date: 25/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152243
Claimant Vehicle No :	SBS3369T	Insured Vehicle No :	SKV4502X
Date of Loss:	06/03/2020	Nature of Claim:	TP
		Claim No:	9103632310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3369T		
Make & Model:	VOLVO B9L, 9.4 (A)	Engine No:	D9191429
Reg. Date:	03/12/2013 (Man. Year: 2013)	Chassis No:	YV3S4P928EA163329
Colour:	Green	Odometer:	358200 km
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8/8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	740.00	740.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	3,220.00	1,300.00	28.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,260.00	3,960.00	1,300.00	24.71
+ GST 7.00/7.00% (S\$)	368.20	277.20	91.00	24.71

Nett Amount (S\$)	5,628.20	4,237.20	1,391.00	24.71
+ Loss of Use (3.0 x S\$200.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,839.20		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 11/03/2020

Date Inspected: 12/03/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Tower Transit Singapore Pte Ltd (HQ)

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S/F DEFLECTOR	Cracked	160.00 F	*160.00 F
2	1		*O/S/F CORNER BUMPER	Cracked	390.00 F	*390.00 F
3	1		*O/S/F LIGHT BEZEL	Cracked	190.00 F	*190.00 F
					Total Parts (\$)	740.00
					740.00	740.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS	New	2,600.00	1,300.00
2	SPRAY PAINTING	New	1,920.00	1,920.00
Gross Labour Cost (S\$)			4,520.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >