



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 8580Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	285.00	285.00
1	HANDLE BALANCER	CUT	48.00	48.00
1	HANDLE BAR HOLDER	NOT NECESSARY	260.00	-
1	CLUTCH LEVER	NOT NECESSARY	50.00	-
1	MIRROR	CUT	125.00	125.00
1	FRONT SIGNAL LAMP	DISTORTED	115.00	115.00
1	GEAR PEDAL	BENT	188.00	188.00
1	FRAME LOWER COVER (L)	CUT	175.00	175.00
1	FRONT FOOT REST	NOT NECESSARY	80.00	-
1	FRONT FOOT REST BRACKET	BENT	250.00	250.00
1	FRONT SPROCKET COVER	CUT	120.00	120.00
1	SIDE STAND	NOT NECESSARY	195.00	-
	LESS 10% DISCOUNT		-	-130.60
			1,891.00	1,175.40
	<u>SPECIAL NETT ITEMS</u>			
1	TOP CRASH BAR (SN)	BENT	380.00	380.00
1	BOTTOM CRASH BAR (SN)	BENT	365.00	365.00
			745.00	745.00
	<u>LABOUR</u>			
	TOWING 2 WAY .		120.00	80.00
	LABOUR .		350.00	200.00
			470.00	280.00
	GRAND TOTAL		3,106.00	2,200.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CC4/FCI20003939/T1da3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.