

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003952/ADA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900108264

Claimant
Vehicle No : SLF3718U **Insured Vehicle No :** SMM1434C

Date of Loss: 11/03/2020 Nature of Claim: TP Claim No: 3798883860SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3718U		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4404944
Reg. Date:	24/08/2016 (Man. Year: 2016)	Chassis No:	RU11204960
Colour:	Blue	Odometer:	210959 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,989.70	5,685.20	4,304.50	43.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	2,050.00	840.00	29.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,879.70	7,735.20	5,144.50	39.94
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	12,879.70	6,150.00	6,729.70	52.25
+ GST 7.00/7.00% (S\$)	901.58	430.50	471.08	52.25
Nett Amount (S\$)	13,781.28	6,580.50	7,200.78	52.25
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,067.95		

INSPECTION

Date of Assignment: 12/03/2020

Date Inspected: 12/03/2020 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,020.00 F	*1,020.00 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	430.00 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Necessary	55.00 F	*55.00 FL
4	1		*REAR BOOT LID VEZEL LOGO	Necessary	38.10 F	*38.10 FL
5	2		*REAR BOOT LID SIDE REFLECTOR	Cut	716.00 F	*716.00 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	237.00 F	*237.00 FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	284.20 F	*284.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	122.20 F	*- FL
10	1		*REAR BOOT LID CENTER MOULDING	Cracked	352.00 F	*352.00 FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	385.00 F	*285.00 FL
13	2		*REAR TAIL LAMP	Cut	770.00 F	*770.00 FL
14	2		*TAIL LAMP LOWER PANEL	Repair	430.00 F	*- FL
15	1		*REAR END PANEL	Distorted	420.00 F	*420.00 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	188.00 F	*188.00 FL
17	1		*REAR BUMPER	Deformed	845.20 F	*845.20 FL
18	2		*REAR BUMPER SIDE BRACKET	Necessary	176.00 F	*96.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
20	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
21	1		*REAR FENDER INNER COWLING PLASTIC	O/S Deformed	430.00 F	*215.00 FL
22	1		*REAR EXHAUST	Bent	855.00 F	*597.00 FL
23	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	122.00 F	*- FL
24	1		*REAR WINDSCREEN MOULDING	Necessary	158.00 F	*158.00 FL
25	1		*REAR SPARE TIRE PANEL LOWER COVER	Deformed	428.00 F	*252.00 FL
26	2		*REAR SPARE TIRE PANEL LOWER PUMP	Not Necessary	580.00 F	*- FL
27	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	200.00 F	*- FL
28	1		*TOOLS TRAY SPONGE	Deformed	258.00 F	*258.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,989.70	7,056.50
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,371.30
Total Parts (\$)	9,989.70	5,685.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REAR EXHAUST	New	280.00	80.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
6	TUFF KOTE	New	120.00	60.00
7	TO CHECK WIRING SYSTEM	New	80.00	30.00
8	PANEL BEATING	New	1,000.00	800.00
9	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (\$)			2,890.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >