Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG20003953/T1VD3E2

Date: 25/08/2020

REFERENCE

Singapore 079120

Insured/Claimant: FAN JIA Policy No:

Date of Loss: 07/03/2020 Nature of Claim: OD Claim No: 4748006708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM5888A

Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A) Engine No: CHZC27831

Reg. Date: 22/05/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V6K1025304

Colour: White Odometer: 12299 km

Engine Capacity: 999 cc Market Value/New Car Price: \$\$96,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,453.00	2,661.20	3,791.80	58.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,955.00	4,263.20	4,691.80	52.39
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,355.00	3,663.20	4,691.80	56.16
+ GST 7.00/7.00% (S\$)	584.85	256.42	328.43	56.16
Nett Amount (S\$)	8,939.85	3,919.62	5,020.23	56.16

INSPECTION

Date of Assignment: 13/03/2020

Date Inspected: 12/03/2020 Inspected At: 281 ALEXANDRA ROAD

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,894.00 FS	*1,515.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - CENTRE	Not Necessary	151.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENT	RE Not Necessary	505.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	280.00 FS	*- FS
6	1	*FRONT BUMPER COVER TRIM - RH	Not Necessary	153.00 FS	*- FS
7	1	*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS
8	1	*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
9	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	177.00 FS	*- FS
10	1	*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	681.00 FS	*- FS
11	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	178.00 FS	*- FS
12	1	*FOAM FILLER PIECE COVER	Not Necessary	115.00 FS	*- FS
13	1	*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
14	1	*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
15	1	*SIGNAL HORN - RH LOW TONE	Not Necessary	188.00 FS	*- FS
16	1	*RADIATOR AIR GUIDE - RH	Not Necessary	23.00 FS	*- FS
17	1	*LIFT CYLINDER - RH	Not Necessary	134.00 FS	*- FS
18	1	*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
19	1	*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Fra	nchise	part. S=SpcNett.	T-4-1 D-4- (04)	0.450.00	0.004.00
			Total Parts (S\$)	6,453.00	2,661.20

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00					
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00					
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00					
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00					
	Gross Labour Cost (S\$)		2,502.00	1,602.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >