VEHICLES & EQUIPMENT DIVISIO Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

| Our Ref: TP / SLU5114U Type of Claim : | ТР | Vehicle No. Make & Model Year of Manufacture | : SLU5114U : BLUECAR / BLUECARBI |
|--|--|---|---|
| MS FIRST INSURANCE | CE LIMITED | Chassis No. Engine No. Policy No. Time of Accident Case Owner | VL4BCEB4RHT002977 : -921955Q16W381345632 : 12:00:00 BLUECAR EAST ASIA PTE |
| Repair Estimates | | TP Vehicle No. | : SHC7990K |
| Parts (a) Cost / List Price Items Plus/Less | \$ 1,704.00 \$ 340.80 \$ 2,044.80 \$ - \$ - \$ - \$ 45.00 \$ 2,089.80 \$ 650.00 \$ 2,739.80 | | |
| Name of Surveyor | | | |
| Company | : | | |
| Survey conducted on | : | at | |
| Remarks By Surveyor | | | |
| (a) The repair of this vehicle is a | authorized / is not auth | orized until further notice. | |
| (b) Recommended Days of Rep | oair : | day(s) | |
| (c) Resurvey | : Required / Not | t Required | |
| (d) Excess | :\$ | | |
| (e) Signature of surveyor | : | Date: _ | |



No . 39 DEFU LANE 12, SINGAPORE 539139 Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

| Vehicle No | : SLU5114U | Case Owner | BLUECAR EAST : ASIA PTE LTD |
|--------------|---------------------------|------------------|------------------------------|
| Make & Model | : BLUECAR / BLUECARBLUECA | Year Manufacture | : 2017 |
| Chassis No | : VL4BCEB4RHT002977 | Engine No | : <u>-921955Q16W381345</u> |
| Date & Time | : | Supplier | : |
| Order By | * | Type of Claim | · TD |

| S/No | Part Description | QTY | | Cost Price | | | List | Nett | 0/01 |
|------|--------------------------------------|-----|------|------------|----|----------|--|-------|----------|
| S/NO | Part Description | QIY | | Unit | Su | b-Total | Price | Price | S/N |
| 1 | REAR BUMPER ASSY | 1 | \$: | 1,364.00 | \$ | 1,364.00 | | | |
| 2 | REAR BUMPER SCREW | 10 | \$ | 2.00 | \$ | | | | |
| 3 | REAR BUMPER REFLECTOR RH | 1 | \$ | 122.00 | \$ | 122.00 | | | |
| 4 | REAR BUMPER REINFORCEMENT | 1 | \$ | 80.00 | \$ | 80.00 | | | |
| 5 | REAR BUMPER REINFORCEMENT BRACKET RH | 1 | \$ | 42.00 | \$ | 42.00 | | | |
| 6 | NUMBER PLATE LAMP LH | 1 | \$ | 38.00 | \$ | | | | |
| 7 | NUMBER PLATE LAMP RH | 1 | \$ | 38.00 | \$ | 38.00 | | | |
| 8 | REAR NUMBER PLATE W CASING | 1 | | | | | | | \$ 45.00 |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |
| 13 | | | | | | | | | |
| 14 | | | | | | | | | |
| 15 | | | | | | | | | |
| 16 | | | 12 | | | | | | |
| 17 | | | | | | | | | |
| 18 | | | | | | | | | |
| 19 | | | | | | | | | |
| 20 | | | | | | | Time to the second seco | | |
| 21 | | | | | | | | | |
| 22 | | | | | | | | | |
| 23 | | | | | | | | | |
| 24 | | | | | | | | | |
| 25 | h h | | | | | | | -4 | |
| 26 | | | | | | | | | |
| 27 | | | | | | | | | |
| 28 | | | | | | | | | |
| 29 | | | | | | | | | |
| 30 | | 87 | | | | | | | 1 |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

BLUECAR EAST ASIA

Vehicle No.

SLU5114U

Case Owner

PTFLTD

Make & Model:

/ BLUECARBLUECAR / BLUECAR Year of Manufacture

2017

| S/No | Labour Description | Esimated Price | Adjusted Price | |
|------|--|-------------------|-------------------|--|
| 1 | TO REPAIR,REPLACE REAR BUMPER, REFLECTOR, NUMBER PLATE | \$400.00 | | |
| | LAMP AND AFFECTED AREA | | | |
| | | | | |
| . 2 | TO APPLY TUFF KOTE | \$150.00 | | |
| | | | | |
| 3 | TO CHECK WIRING | \$100.00 | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | -9 | ~ | | |
| | | | | |
| | | | | |
| | | | | |
| | TOTAL | \$650.00 | | |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.