

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2020 Edit Reg		13 Mar 2020 00:00 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN PHUAY SUAN , ID: S0055849D									
Main Claimant: EZORA SIGNATURES PTE LTD									
Vehicle Reg. No.: SLR3757T		Date of Loss: 10/03/2020 10:00 - :59 [30 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2149895372SG		Policy/Cover Note No.: 1900164955 (Comprehensive)							
Vehicle Reg. No. (Insured): SMP211U		Policy No. (Claimant): Excess:							
Repairer: Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity, 575722 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/03/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (23/06/2020): Alert - Adj Mandate Approved (S\$2627.45) - SLR3757T - Claim Handler: Lee, Ming-Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR3757T (2149895372SG)
[SMP211U]
TP
EZORA SIGNATURES PTE LTD
Mar 10 2020 10:00AM
[TAN PHUAY SUAN]
Poon Siang Sew

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/04/20 12:01	General View		Load JPG	☒
2	20/04/20 12:01	General View		Load JPG	☒
3	20/04/20 12:01	General View		Load JPG	☒
4	20/04/20 12:01	General View		Load JPG	☒
5	20/04/20 12:01	General View		Load JPG	☒
6	20/04/20 12:01	General View		Load JPG	☒
7	20/04/20 12:01	General View		Load JPG	☒
8	20/04/20 12:01	General View		Load JPG	☒
9	20/04/20 12:01	General View		Load JPG	☒
10	20/04/20 12:01	General View		Load JPG	☒
11	20/04/20 12:01	General View		Load JPG	☒
12	20/04/20 12:01	General View		Load JPG	☒
13	20/04/20 12:01	Odometer Reading		Load JPG	☒
14	20/04/20 12:01	General View		Load JPG	☒
15	20/04/20 12:01	Chassis Number		Load JPG	☒
16	20/04/20 12:02	Reinspection Photo		Load JPG	☒
17	20/04/20 12:02	Reinspection Photo		Load JPG	☒

Documentation

1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/20 15:49	ACKNOWLEDGEMENT EMAIL TO AIG DD13032020		Load PDF	
2	13/03/20 15:49	EMAIL FROM AIG DD13032020		Load PDF	
3	13/03/20 15:49	NOTIFICATION FROM WKSP + TP GIA REPORT		Load PDF	
4	13/03/20 15:49	LTA SEARCH		Load PDF	
5	18/03/20 16:18	TP ESTIMATE-MARKED		Load PDF	
6	20/04/20 09:59	LETTER TO OI		Load PDF	
7	20/04/20 11:58	LOD		Load PDF	
8	06/07/20 13:19	Authorisation to Act		Load PDF	
9	06/07/20 13:19	Release Voucher		Load PDF	
10	06/07/20 13:19	WORKSHOP INVOICE		Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	16/03/20 12:14	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMP211U (Insd veh)	Model:	KIA CERATO FORTE 1.6 (A)
	SLR3757T (TP veh)		
Date of Accident:	10/03/2020		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$	6,504.00		
Final Repair Cost	:	\$	2,300.00		
Loss of Use	:	\$	320.00		4.00 days at \$80.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$	7.45		
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$	2,627.45		
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)					
A) For Non GIA Registered Workshop:			Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:			BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)			Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Poon Siang Seow	:	\$ 2,627.45
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

06 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20003974/KDS3S2**Date:** 06/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900164955
Claimant Vehicle No :	SLR3757T	Insured Vehicle No :	SMP211U
Date of Loss:	10/03/2020	Nature of Claim:	TP
		Claim No:	2149895372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3757T	Engine No:	G4FGGH654506
Make & Model:	KIA CERATO FORTE, 1.6 (A)	Chassis No:	KNAFX411MH5676075
Reg. Date:	14/08/2017 (Man. Year: 2016)	Odometer:	178885 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Roadstone 7 mm	Rear Left Side:	Roadstone 7 mm
Front Right Side:	Roadstone 7 mm	Rear Right Side:	Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,524.00	2,058.50	2,465.50	54.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	830.00	1,150.00	58.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,504.00	2,888.50	3,615.50	55.59
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,504.00	2,300.00	4,204.00	64.64
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,627.45		

INSPECTION

Date of Assignment:	13/03/2020	
Date Inspected:	16/03/2020	Inspected At: Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL BOOT	Bent	1,073.00 F	*885.00 FL
2	2		*REAR BOOT REFLECTOR	Serviceable	560.00 F	*- FL
3	2		*REAR TAIL LAMP	Serviceable	640.00 F	*- FL
4	1		*REAR TAIL BOOT RUBBER	Serviceable	201.00 F	*- FL
5	1		*REAR TAIL BOOT LOCK	Repair	240.00 F	*- FL
6	1		*REAR TAIL BOOT LOGO	Necessary	45.00 F	*45.00 FL
7	1		*REAR TAIL BOOT BADGE FORTEK	Necessary	65.00 F	*65.00 FL
8	1		*REAR TAIL BOOT BADGE CERTO	Necessary	55.00 F	*55.00 FL
9	1		*REAR BUMPER	Buckled	668.00 F	*668.00 FL
10	1		*REAR BUMPER LOWER	Dented	347.00 F	*347.00 FL
11	2		*REAR BUMPER RETAINER	Serviceable	60.00 F	*- FL
12	2		*REAR BUMPER REFLECTOR	Serviceable	50.00 F	*- FL
13	1		*W/S GLASS MOULDING	Not Necessary	120.00 F	*- FL
14	1		*REAR BUMPER SENSOR	Dented	350.00 FS	*200.00 FS
15	1		*NUMBER PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,524.00	2,265.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	206.50
Total Parts (\$)	4,524.00	2,058.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING.	New	100.00	30.00
2	PANEL BEATING.	New	980.00	400.00
3	SPRAY PAINTING.	New	900.00	400.00
Gross Labour Cost (\$\$)			1,980.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >