LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20003981/HTD3S2

Date: 12/05/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte.

RGO insurance Pte. Policy No:

Claimant Vehicle SDS3010D No:

Insured Vehicle SDT2829K

Date of Loss: 10/03/2020 Nature of Claim: TP Claim No: CDMPG20000456

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDS3010D

 Make & Model:
 TOYOTA HARRIER, 2.0 Elegance (A)
 Engine No:
 3ZRB696348

 Reg. Date:
 14/03/2016 (Man. Year: 2015)
 Chassis No:
 ZSU600067994

 Colour:
 Silver
 Odometer:
 68125 km

Engine Capacity: 1986 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,620.62	3,771.74	4,848.88	56.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	660.00	1,110.00	62.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,390.62	4,431.74	5,958.88	57.35
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	10,390.62	3,550.00	6,840.62	65.83

INSPECTION

Date of Assignment: 13/03/2020

Date Inspected: 16/03/2020 Inspected At: NO.1 KAKI BUKIT AVE 6 #01-83

Singapore 417883

Cheng Motor Work Company (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Mar 2020)

TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-SUV

(Price-denominated Standard List) Labour: Repairer's

Print Code: LKK Auto Consultants Pte Ltd/SDS3010D/12/05/2020 16:53

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP L/H	Scratched	3,187.40 F	*2,500.80 FL
2	1		*FRONT BUMPER	Crushed	1,710.40 F	*1,482.30 FL
3	1		*FRONT BUMPER SIDE RETAINER L/H	Serviceable	141.30 F	*- FL
4	1		*FRONT BUMPER FOG LAMP	Cracked	399.45 F	*399.45 FL
5	1		*FRONT BUMPER FOG LAMP COVER	Scratched	133.10 F	*92.30 FL
6	1		*FRONT BUMPER INNER SIDE SPONGE	Serviceable	203.12 F	*- FL
7	1		*FRONT BUMPER INNER SPONGE	Serviceable	110.80 F	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	398.34 F	*- FL
9	1		*FRONT BUMPER CORNER RETAINER	Serviceable	102.10 F	*- FL
10	1		*FRONT BUMPER TOP BEAM	Serviceable	145.00 F	*-FL
11	1		*FRONT FENDER INNER SHIELD	Serviceable	335.95 F	*- FL
12	1		*BUMPER COVER LID	Scratched	310.16 F	*280.80 FL
13	1		*SET FRONT BUMPER CLIP	Necessary	110.00 FS	*30.00 FS
14	1		*FRONT FENDER INNER SHIELD CLIP 15pcs	Necessary 10pcs Only	133.50 FS	*25.00 FS
15	1		*FRONT TYRE SPORT RIM (LOCAL REPAIR)	Scratched	1,200.00 FS	*150.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
Sub Total (S\$)			8,620.62	4,960.65		
	- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	1,188.91
				Total Parts (S\$)	8,620.62	3,771.74

LKK Auto Consultants Pte Ltd/SDS3010D/12/05/2020 16:53. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO KNOCKING, REPAIRING, REPLACED OF PARTS.	New	750.00	300.00				
2	TO PUTTY AND SPRAY PAINTING ON DAMAGE PORTION	I. New	800.00	250.00				
3	TO REMOVE / RENEW HEADLAMP, TEST FOR PROPER FUNCTIONING AND FOCUS.	New	60.00	30.00				
4	TO REWIRING / CHECKING.	New	60.00	40.00				
5	TO APPLY RUST PROOFING.	New	100.00	40.00				
		Gross Labour Cost (S\$)	1,770.00	660.00				

LKK Auto Consultants Pte Ltd/SDS3010D/12/05/2020 16:53. Not valid without Reference section.

< END OF ESTIMATES >