

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003982/KES3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2000003846

**Claimant**  
**Vehicle No :** SBQ2883S **Insured Vehicle No :** SMA53M

Date of Loss: 11/03/2020 Nature of Claim: TP Claim No: 2754330920SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBQ2883S</b>		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520262860
Reg. Date:	26/03/2015 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0301483
Colour:	Metallic Grey	Odometer:	96706 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,191.18	5,683.76	507.42	8.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	2,530.00	220.00	8.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,941.18</b>	<b>8,213.76</b>	<b>727.42</b>	<b>8.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,550.00</b>		
<b>(S\$)</b>	8,941.18	6,550.00	2,391.18	26.74
<b>+ GST 7.00/7.00% (S\$)</b>	625.88	458.50	167.38	26.74
<b>Nett Amount (S\$)</b>	<b>9,567.06</b>	<b>7,008.50</b>	<b>2,558.56</b>	<b>26.74</b>
<b>+ Car Rental (7.0 x S\$85.00/day + 7.00% GST) (S\$)</b>		636.65		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>7,653.15</b>		

### INSPECTION

Date of Assignment: 12/03/2020

Date Inspected: 13/03/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun  
Industrial Park A  
Singapore 768761

Estimated Period of Repair: 9.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,127.00 FL	*1,127.00 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked	105.20 FL	*52.60 FL
3	2		*REAR BUMPER RETAINER	Distorted	75.80 FL	*75.80 FL
4	6		*REAR BUMPER CLIPS	Necessary	28.80 FL	*28.80 FL
5	2		*REAR BUMPER TOW	Missing	33.60 FL	*33.60 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	563.80 FL	*563.80 FL
7	1		*REAR BOOT	Bent	1,004.80 FL	*1,004.80 FL
8	1		*REAR BOOT EMBLEM 3	Necessary	56.07 FL	*56.07 FL
9	1		*REAR BOOT EMBLEM SKY	Necessary	66.30 FL	*66.30 FL
10	1		*REAR BOOT INNER LOCK	Dented	185.80 FL	*185.80 FL
11	1		*REAR BOOT INNER RUBBER (50%)	Dented / Distorted	108.32 FS	*67.70 FS
12	1		*REAR BOOT SPONGE	Serviceable	135.30 FL	*- FL
13	1		*REAR BOOT LOGO	Necessary	77.60 FL	*77.60 FL
14	2		*TAIL LAMP	Cracked	1,068.80 FL	*1,068.80 FL
15	1		*TAIL LAMP PANELS	O/S Repair / N/S Bent	791.20 FL	*395.60 FL
16	1		*REAR PANEL	Bent	530.20 FL	*530.20 FL
17	1		*REAR PANEL INNER TOP GARNISH	Distorted	99.75 FL	*99.75 FL
18	1		*REAR LH FENDER	Buckled	1,232.70 FL	*1,232.70 FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	77.10 FL	*77.10 FL
20	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
22	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,643.14</b>	<b>7,019.02</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,451.96</b>	<b>1,335.26</b>
<b>Total Parts (\$\$)</b>	<b>6,191.18</b>	<b>5,683.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE AND REFIX SEAT ,CARPET ,GARNISH ,TOP ROOF LINING	New	120.00	100.00
4	REMOVE AND REFIX REAR BUMPER ASSY ,TAIL LAMP ,REAR BOOT ,REFLECTORS .TO STRAIGHTEN ,KNOCK AND REPAIR REAR BOTH CHASSIS ,CUTTING ,WELDING AND RENEW REAR PANEL,TALLAMP PANELS ,REAR LH FENDER AND REALIGN THE SAME	New	1,300.00	1,200.00
5	PUTTY AND RESPRAY ON REAR BOOT ,HINGES ,REAR PANEL ,REAR BOTH FENDERS ,REAR SPARE TYRE COMPARTMENT,REAR BUMPER AND REAR AFFECTED AREA	New	1,100.00	1,000.00
6	RUSTPROOFING	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,750.00</b>	<b>2,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >