

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2020 Edit Reg		13 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	POH PEI PEI , ID: S7401877G		
Main Claimant:	YUNG YEW TONG , ID: S7240979E		
Vehicle Reg. No.:	SLS6990K	Date of Loss:	14/02/2020 00:00 - :59 [99 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1202000013262	Policy/Cover Note No.:	PNPV2019-00009824 (Comprehensive) Coverage: 30/05/2019 - 29/05/2020
Vehicle Reg. No. (Insured):	SGM9979R	Policy No. (Claimant):	
		Excess:	
Repairer:	Kompressor Automotive Workshop (HQ) 8 Kaki Bukit Avenue 4 #02-48 Premier, 415875 Kaki Bukit - Tel: 67457574		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 24/03/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS6990K (1202000013262)
[SGM9979R]**

TP

YUNG YEW TONG

Feb 14 2020 12:00AM

[POH PEI PEI]

Kompressor Automotive Workshop

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/20 10:38	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
42	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
43	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
44	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
45	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
46	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
47	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
48	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
49	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
50	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
51	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
52	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
53	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
54	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
55	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
56	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
57	26/03/20 11:01	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
58	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
59	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
60	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
61	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
62	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
63	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
64	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
65	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
66	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
67	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
68	26/03/20 11:02	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/20 16:54	EMAIL FROM VENESSA TO ARRANGE FOR SURVEY	Load PDF	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/03/20 10:18	SGM9979R OI GIA	Load PDF	<input checked="" type="checkbox"/>
2	17/03/20 10:18	SLS6990K PRI - Tng Soon Chye & Co & TP GIA	Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/FWD20003985/FTD3S2**Date:** 07/04/2020REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00009824
Claimant Vehicle No :	SLS6990K	Insured Vehicle No :	SGM9979R
Date of Loss:	14/02/2020	Nature of Claim:	TP
		Claim No:	1202000013262

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6990K	Engine No:	27186030332642
Make & Model:	MERCEDES-BENZ E200, 1.8 (A)	Chassis No:	WDD2120482A511877
Reg. Date:	18/10/2011 (Man. Year: 2011)	Odometer:	133950 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/03/2020		
Date Inspected:	18/03/2020	Inspected At:	Kompressor Automotive Workshop (HQ) 8 Kaki Bukit Avenue 4 #02-48 Premier Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: PARASURAM SHANMUGAM**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

4/7/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Apr 2020)

Parts: 143 MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS6990K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >