

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003989/R1KS3Q2**Date:** 13/08/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994044

Claimant
Vehicle No : SMK3569U **Insured Vehicle No :** SKB9066K

Date of Loss: 13/03/2020 Nature of Claim: TP Claim No: 2064888669SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3569U	Engine No:	16165540B48B20B
Make & Model:	BMW 630CI, 3.0 (A)	Chassis No:	WBAJX62040BJ24273
Reg. Date:	15/03/2019 (Man. Year: 2018)	Odometer:	9800 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,026.50	10,362.50	12,664.00	55.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,160.00	7,596.00	5,564.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	36,186.50	17,958.50	18,228.00	50.37
+ GST 7.00/7.00% (S\$)	2,533.06	1,257.10	1,275.96	50.37
Nett Amount (S\$)	38,719.56	19,215.60	19,503.96	50.37
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		20,223.05		

INSPECTION

Date of Assignment: 13/03/2020

Date Inspected: 13/03/2020 Inspected At:

 Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Not Necessary	83.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*LH TAILPIPE TRIM CHROME	Scratched	188.20 FS	*188.20 FS
4	1		*RH TAILPIPE TRIM CHROME	Serviceable	188.20 FS	*- FS
5	1		*INTERMEDIATE EXHAUST	Serviceable	592.05 FS	*- FS
6	1		*REAR SILENCER WITH EXHAUST FLAP	Bent	2,168.15 FS	*2,168.15 FS
7	1		*FRONT MUFFLE	Bent	1,432.60 FS	*1,432.60 FS
8	1		*TAILGATE ALUMINIUM	Bent	1,749.70 FS	*1,749.70 FS
9	1		*INTERIOR TAIL TRIM	Serviceable	560.95 FS	*- FS
10	1		*OUTER PANEL TAIL TRIM	Serviceable	713.95 FS	*- FS
11	1		*LH TRUNK LID HINGE	Serviceable	119.40 FS	*- FS
12	1		*RH TRUNK LID HINGE	Serviceable	119.40 FS	*- FS
13	1		*REAR BUMPER CARRIER	Bent	939.15 FS	*939.15 FS
14	1		*ABRASION GUA	Not Necessary	5.55 FS	*- FS
15	1		*ABRASION GUA	Not Necessary	5.55 FS	*- FS
16	1		*REAR BUMPER BOTTOM REINFORCEMENT	Cracked	88.15 FS	*88.15 FS
17	1		*REAR BUMPER CENTRE GUIDE	Cracked	73.80 FS	*73.80 FS
18	1		*LH GUIDE FOR SIDE BUMPER	Cracked	67.45 FS	*67.45 FS
19	1		*RH GUIDE FOR SIDE BUMPER	Serviceable	67.45 FS	*- FS
20	1		*REAR BUMPER TOWING EYE FLAP (M)	Serviceable	87.60 FS	*- FS
21	1		*REAR BUMPER TRIM PANEL PAINTED (M)	Deformed	455.35 FS	*455.35 FS
22	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,821.30 FS	*1,821.30 FS
23	2		*EMBLEM GROMMET	Not Necessary	1.70 FS	*- FS
24	1		*LETTERING 630I	Not Necessary	64.45 FS	*- FS
25	1		*LETTERING GT	Not Necessary	64.45 FS	*- FS
26	1		*PLAQUE 82MM	Not Necessary	71.60 FS	*- FS
27	1		*TRUNK LID POWER LOCK DRIVE	Not Necessary	612.10 FS	*- FS
28	1		*LOCK TRUNK LID	Not Necessary	229.10 FS	*- FS
29	10		*BUMP STOP	Not Necessary	37.50 FS	*- FS
30	1		*REAR WINDOW GREEN (ESG)	Not Necessary	967.05 FS	*- FS
31	4		*VELCRO	Not Necessary	10.40 FS	*- FS
32	1		*TRIM ,LUGGAG	Not Necessary	180.25 FS	*- FS
33	1		*LOADING SILL	Not Necessary	135.25 FS	*- FS
34	1		*FLOOR CARPER	Not Necessary	721.00 FS	*- FS
35	1		*LH GUTTER STRIP	Not Necessary	55.10 FS	*- FS
36	1		*RH GUTTER STRIP	Not Necessary	55.10 FS	*- FS
37	1		*BOOT LID INSIDE COVER	Not Necessary	254.20 FS	*- FS
38	1		*SPOILER MODU	Not Necessary	1,370.05 FS	*- FS
39	1		*COVERING LEF	Not Necessary	37.25 FS	*- FS
40	1		*COVERING RIG	Not Necessary	37.25 FS	*- FS
41	1		*TRUNK LID SEALING	Not Necessary	166.50 FS	*- FS
42	1		*TRUNK LID SEALING	Not Necessary	166.50 FS	*- FS
43	1		*FUEHRUNG	Not Necessary	41.70 FS	*- FS
44	1		*LH REFLECTOR	Not Necessary	38.85 FS	*- FS
45	1		*RH REFLECTOR	Not Necessary	38.85 FS	*- FS
46	1		*REAR LH LIGHT SIDE PANEL LED	Not Necessary	637.95 FS	*- FS
47	1		*REAR RH LIGHT SIDE PANEL LED	Not Necessary	637.95 FS	*- FS
48	1		*REAR LH LIGHT TAILGATE LED	Not Necessary	446.55 FS	*- FS
49	1		*REAR RH LIGHT TAILGATE LED	Not Necessary	446.55 FS	*- FS
50	1		*SET OF SEALS	Not Necessary	27.70 FS	*- FS
51	1		*SET OF SEALS	Not Necessary	27.70 FS	*- FS
52	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS
53	4		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Not Necessary	1,480.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FILLER FOAM	Not Necessary	141.40 FS	*- FS
55	1		*BLIND RIVET AVIBVLB (52 PCS)	Not Necessary	28.60 FS	*- FS
56	1		*BLIND RIVET AVIBVLB (30 PCS)	Not Necessary	16.50 FS	*- FS
57	6		*SCREW (SF PLUS M5X15)	Not Necessary	3.30 FS	*- FS
58	1		*(S/L) CLEANER R2 500ML	Not Necessary	12.50 FS	*- FS
59	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	331.80 FS	*- FS
60	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	114.45 FS	*- FS
61	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
62	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
63	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
64	1		*PUNCH RIVET N4 (26 PCS)	Not Necessary	14.30 FS	*- FS
65	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Not Necessary	27.85 FS	*- FS
66	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS
67	2		*CLAMPING BUSH	Necessary	134.30 FS	*134.30 FS
68	1		*INTERMEDIATE PIPE	Bent	592.05 FS	*592.05 FS
69	1		*REAR SILENCER LH HEAT INSULATION	Bent	166.55 FS	*166.55 FS
70	1		*REAR SILENCER HEAT INSULATOR	Bent	287.65 FS	*287.65 FS
71	1		*REAR UNDERBODY PANELLING	Deformed	48.10 FS	*48.10 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					23,026.50	10,362.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT SILENCER AND INTERMEDIATE PIPE INCLUDING TO ALIGN SYSTEM AND CHECK FOR LEAK	New	451.00	451.00
2	REPLACE REAR BOOT LID REAR BUMPER ,TAIL PANEL INCLUDE REMOVE ATTACHMENT ETC	New	4,250.00	2,550.00
3	SPRAY PAINTING BOTH REAR SIDE FENDER ,REAR BOOT LID ,REAR BUMPER ,TAIL PANEL AND FLOOR PANEL	New	5,120.00	3,015.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	230.00
6	TO REPLACE WINDSCREEN GLASS	New	574.00	574.00
7	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
8	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
9	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
10	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
11	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
12	TO REPLACE FRONT SEAT CRASH-ACTIVE HEAD RESTRAINT AIR BAGS INCLUDING RESET AND CONDUCT CHECK FOR FUNCTION	New	531.00	0.00
Gross Labour Cost (\$\$)			13,160.00	7,596.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >