

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004021/GCF3E2

Date: 26/01/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29074276		
Claimant Vehicle No :	SMJ8603B	Insured Vehicle No :	SLL8563J		
Date of Loss:	12/03/2020	Nature of Claim:	TP	Claim No:	621789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8603B	Engine No:	MR20453000W
Make & Model:	NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A)	Chassis No:	SJNFBAJ11U1916191
Reg. Date:	06/03/2017 (Man. Year: 2017)	Odometer:	67448 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,656.26	4,308.34	2,347.92	35.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,130.00	1,160.00	50.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,946.26	5,438.34	3,507.92	39.21
+ GST 7.00/7.00% (S\$)	626.24	380.68	245.56	39.21
Nett Amount (S\$)	9,572.50	5,819.02	3,753.48	39.21

INSPECTION

Date of Assignment:	16/03/2020		
Date Inspected:	16/03/2020	Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jan 2021)

Parts: M1-SUV NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ8603B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	796.70 FN	*717.00 FN
2	1		*REAR BUMPER SIDE RETAINER - RH	Not Necessary	55.10 FN	*- FN
3	1		*REAR FENDER DUST COVER - RH	Not Necessary	99.10 FN	*- FN
4	1		*REAR FENDER PROTECTOR - RH	Scratched	654.00 FN	*483.00 FN
5	1		*REAR DOOR - RH	Buckled	1,166.20 FN	*1,104.80 FN
6	1		*REAR DOOR LOCK - RH	Not Necessary	172.30 FN	*- FN
7	1		*REAR DOOR PROTECTOR - RH	Scratched	280.40 FN	*188.90 FN
8	1		*REAR DOOR RUBBER	Not Necessary	189.80 FN	*- FN
9	1		*REAR UPPER ARM - RH	Not Necessary	266.40 FN	*- FN
10	1		*REAR KNUCKLE ARM - RH	Bent	1,322.80 FN	*581.30 FN
11	1		*REAR LOWER ARM - RH	Bent	167.60 FN	*167.60 FN
12	1		*REAR TYRE - RH	Torn	280.00 FS	*140.00 FS
13	1		*REAR SPORT RIM - (RAVS)	Cut	1,200.00 FS	*800.00 FS
14	1		*REAR SHOCK ABSORBER - RH	Bent	172.20 FS	*150.00 FS
15	1		*REAR HUB BEARING - RH	Bent	350.70 FS	*300.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,173.30	4,632.60
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	517.04	324.26
Total Parts (\$\$)	6,656.26	4,308.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	400.00
2	RUST PROOFING	New	60.00	0.00
3	TOWING (KING ROLLER)	New	100.00	80.00
4	ALIGNMENT	New	100.00	60.00
5	TO REMOVE & REPLACE REAR UNDER CARRIAGE	New	280.00	150.00
6	TO REMOVE & REPLACE DOOR ASSY	New	80.00	40.00
7	TO SPRAY PAINT	New	820.00	400.00
Gross Labour Cost (\$\$)			2,290.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >