

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date Reference

INV No.

AC2006918

08/10/2020 CC4/FCI20004026/Aea3q2

Code FCI2

## **PROFESSIONAL SERVICE FEE**

Vehicle No. SJZ 2123K

Insured Veh. SHA 3797P

Claim No. D20001463MFSH

Policy No. D-20094922MFSH

Accident Date 12/03/2020

Inspection Date 13/03/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
MS F	MS FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20004026/Aea3q2				
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 08-10-2020 Code: FCI2			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHA 3797P	Veh. Inspected	SJZ 2123K	
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
	Claim No.	D20001463MFSH	Excess (\$)	0.00	
	Assign From	CHRIS	Assign Date	13/03/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	BMW 318	c.c	1995	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	WBAPF72050A793919	Colour	BLACK	
	Odometer	159207	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	DUNLOP	6 mm	
	L/H Front Tyre	225/40 R18	DUNLOP	6 mm	
	R/H Rear Tyre	225/40 R18	DUNLOP	6 mm	
	L/H Rear Tyre	225/40 R18	DUNLOP	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT O/S PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	12/03/2020	Inspection Date	13/03/2020	
	Survey held at	KANG CAR REPAIRERS PTE LTD  NO.1 KAKI BUKIT AVE 6  #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 2123K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT FENDER RH	DENTED	796.70	796.70
1	FRT FENDER COWLING RH	TORN	266.70	266.70
1	FRT BUMPER	TORN	1,528.80	1,528.80
1	FRT BUMPER RETAINER RH	NECESSARY	39.40	39.40
1	FRT FOG LAMP RH	NOT NECESSARY	360.40	-
1	FRT FOG LAMP SIDE COVER RH	NOT NECESSARY	71.80	-
1	HEADLAMP RH	CRACKED	1,455.10	1,455.10
1	HEADLAMP RH RETAINER	CRACKED	69.10	69.10
1	FRT GRILLE RH	CRACKED	187.30	187.30
1	FRT GRILLE LH	CRACKED	187.30	187.30
1	FRT GRILLE TOP RUBBER	NOT NECESSARY	54.40	-
1	FRT SHOCK ABSORBER RH	NOT NECESSARY	774.90	-
1	FRT LOWER ARM RH	NOT NECESSARY	596.10	-
1	FRT KNUCKLE ARM RH	NOT NECESSARY	849.20	-
1	FRT WHEEL HUB RH	NOT NECESSARY	297.10	-
1	FRT BEARING RH	NOT NECESSARY	122.80	-
	LESS 10% DISCOUNT		-765.71	-453.04
			6,891.39	4,077.36
	SPECIAL NETT ITEMS			
1	SET FRT FENDER COWLING CLIPS RH (SN)	NECESSARY	40.00	30.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	SET FRT GRILLE CLIPS (SN)	NECESSARY	40.00	30.00
1	FRT SPORTS RIM RH (SN)	сит	1,000.00	800.00
1	FRT TYRE RH (SN)	NOT NECESSARY	650.00	-
			1,778.00	890.00
	LABOUR			
	TOWING.		100.00	100.00
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE AND REFIT UNDERCARRIAGE.	NOT NECESSARY	380.00	
	TO CHECK WHEEL ALIGNMENT.		120.00	80.00

Report Ref No. CC4/FCI20004026/Aea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY UNDERSEAL.		80.00	40.00
	(FRONT) TO SPRAY PAINTING.		800.00	500.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.		900.00	500.00
			2,430.00	1,250.00
	GRAND TOTAL		11,099.39	6,217.36

RECOMMENDED COST OF LUMP SUM REPAIRS	4,950.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/FCI20004026/Aea3q2



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SJZ 2123K

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3591 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJZ 2123K


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

