

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20004029/KSF3E2

Date: 22/05/2020

REFERENCE

Insured/Claimant:	CHONG LEE LIAN	Policy No:	1800077117		
Date of Loss:	04/03/2020	Nature of Claim:	OD	Claim No:	7881846122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3503B		
Make & Model:	SUBARU FORESTER, 2.0 AWD (A)	Engine No:	FB20YE11318
Reg. Date:	29/06/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG110790
Colour:	Metallic Red	Odometer:	19405 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,921.77	998.13	1,923.64	65.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,049.00	2,068.00	3,981.00	65.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,970.77	3,066.13	5,904.64	65.82
+ GST 7.00/7.00% (S\$)	627.95	214.63	413.32	65.82
Nett Amount (S\$)	9,598.72	3,280.76	6,317.96	65.82

INSPECTION

Date of Assignment:	16/03/2020	
Date Inspected:	16/03/2020 Inspected At:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MUD GUARD, REAR RIGHT	Serviceable	57.60 FL	*- FL
2	1		*MUD GUARD, REAR LEFT	Serviceable	57.60 FL	*- FL
3	1		*WEATHER STRIP-REAR GATE	Serviceable	111.60 FL	*- FL
4	1		*COVER REAR BUMPER	Dented	12.60 FL	*12.60 FL
5	1		*BUMPER-FACE, REAR	Bent	540.00 FL	*540.00 FL
6	1		*BRACKET-REAR BUMPER SIDE, RIGHT	Serviceable	14.40 FL	*- FL
7	1		*BRACKET-REAR BUMPER SIDE, LEFT	Serviceable	14.40 FL	*- FL
8	1		*BACK BEAM COMPLETE-REAR	Bent	288.00 FL	*288.00 FL
9	1		*SKIRT COMPLETE-REAR	Repair	288.00 FL	*- FL
10	1		*FLOOR PAN COMPLETE-REAR, REAR	Repair	432.00 FL	*- FL
11	2		*REFLEX REFLECTOR ASSEMBLY, RIGHT	Serviceable	40.80 FL	*- FL
12	1		*REFLEX REFLECTOR ASSEMBLY, LEFT	Serviceable	20.40 FL	*- FL
13	1		*LETTER MARK-REAR	Not Necessary	39.60 FL	*- FL
14	1		*LETTER MARK-REAR	Not Necessary	64.80 FL	*- FL
15	1		*TAIL PIPE CUTTER	Not Necessary	72.00 FL	*- FL
16	1		*MUFFLER ASSEMBLY-RIGHT	Repair	601.20 FL	*- FL
17	1		*GASKET A	Not Necessary	7.20 FL	*- FL
18	1		*EXHAUST PIPE ASSEMBLY-REAR	Repair	745.20 FL	*- FL
19	1		*GASKET-EXHAUST PIPE REAR	Serviceable	24.00 FL	*- FL
20	1		*COVER-REAR BUMPER	Serviceable	14.40 FL	*- FL
21	1		*CARGO STEP PANEL S/S	Necessary	460.00 FL	*460.00 FL
22	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
23	1		*COVER REAR BUMPER	Bent	14.40 FL	*14.40 FL
24	1		*BOLT	Bent	10.10 FL	*10.10 FL
25	1		*HOLDER JACK	Cracked	100.80 FL	*100.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,131.10	1,425.90
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,209.33	427.77
Total Parts (\$\$)	2,921.77	998.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE REAR BUMPER, END PANEL, FLOOR PAN, TAILGATE AND PANEL	New	1,750.00	1,000.00
2	RESPRAY REAR BUMPER, END PANEL, FLOOR PAN AND PANEL	New	1,400.00	750.00
3	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	New	684.00	0.00
4	REMOVE & REFIX EXHAUST	New	114.00	0.00
5	TO CONDUCT 4 WHEEL ALIGNMENT	New	171.00	0.00
6	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS	New	342.00	0.00
7	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS	New	114.00	0.00
8	TO REMOVE & REFIX FUEL TANK	New	171.00	0.00
9	TO CONDUCT ANTI RUST COATING	New	290.00	0.00
10	TO REMOVE & INSTALL REAR WINDSCREEN	New	300.00	0.00
11	TO CONDUCT REAR LIGHTING TEST	New	28.00	28.00
12	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	New	300.00	0.00
13	TO CONDUCT ANTI RUST COATING	New	290.00	290.00
14	TRANSFER TAILGATE MECHANISM	New	95.00	0.00
Gross Labour Cost (\$)			6,049.00	2,068.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >