

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 5894P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT FLAP | TO REPAIR SEE LABOUR | 1,625.00 | - |
| 1 | FRONT HEADLAMP PANEL RH | TO REPAIR SEE LABOUR | 847.50 | - |
| 1 | FRONT DOME | TO REPAIR SEE LABOUR | 2,500.00 | - |
| | | | 4,972.50 | - |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | NUMBER PLATE (SN) | CRUMPLED | 75.00 | 75.00 |
| 1 | STICKER SMRT (SN) | NECESSARY | 75.00 | 75.00 |
| | | | 150.00 | 150.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT FLAP, FRONT HEADLAMP PANEL RH AND FRONT DOME. | | 1,060.00 | 530.00 |
| | PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS. | | 878.00 | 786.00 |
| | | | 1,938.00 | 1,316.00 |
| | GRAND TOTAL | | 7,060.50 | 1,466.00 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | 1,150.00 |

Report Ref No. NS/INC20004037/Qyf3e2


OI SUN PIN

Asst. Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.