


National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20004037/Qyf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-05-2020 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBE 758Y	Veh. Ir	nspected	SMB 5894P
	Policy No.	5097398185-02	Cover	age (\$)	0.00
	Claim No.	MT/1088115-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	13/03/2020
2. Vehicle Particulars & Condition					
	Make & Model	MAN A95	c.c		10518
	Engine No.	HIDDEN	Year o	f Reg.	2015
	Chassis No.	WMAA95ZZXG7003050	Colou	r	MULTI COLOUR
	Odometer	278146	Steerii	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	275/70 R22.5	FALKE	N	6 mm
	L/H Front Tyre	275/70 R22.5	FALKE	N	6 mm
	R/H Rear Tyre	275/70 R22.5 (D)	FALKE	N	6 mm
	L/H Rear Tyre	275/70 R22.5 (D)	FALKE	N	6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	12/03/2020	Inspec	tion Date	13/03/2020
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				