

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT120004060/EYF3E2

**Date:** 24/07/2020

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30499819000	
Claimant Vehicle No : GBG9027D	Insured Vehicle No : SMC9347X	
Date of Loss: 09/03/2020	Nature of Claim: TP	Claim No: SNM20D201250/C02/BEN

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG9027D</b>			
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30026565N	
Reg. Date:	27/11/2017 (Man. Year: 2017)	Chassis No:	JN1SC2F24Z0860395	
Colour:	Silver	Odometer:	49503 km	
Engine Capacity:	2953 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/80R15	Rear Tyre Size:	185/80R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,043.16	4,595.29	4,447.87	49.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,810.00	1,240.00	40.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,093.16</b>	<b>6,405.29</b>	<b>5,687.87</b>	<b>47.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>846.52</b>	<b>448.37</b>	<b>398.15</b>	<b>47.03</b>
<b>Nett Amount (S\$)</b>	<b>12,939.68</b>	<b>6,853.66</b>	<b>6,086.02</b>	<b>47.03</b>

#### INSPECTION

Date of Assignment:	23/07/2020	
Date Inspected:	17/03/2020	Inspected At: Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	8.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Jul 2020)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG9027D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER W REINFORCEMENT	Cut	945.10 FL	*945.10 FL
2	10		*FRONT BUMPER CLIPS	Necessary	150.00 FL	*40.00 FL
3	2		*FRONT BUMPER BOLT	Not Necessary	50.00 FL	*- FL
4	1		*FRONT CENTRE PANEL	Dented	1,412.70 FL	*1,412.70 FL
5	1		*FRONT RADIATOR GRILLE	Crushed	438.70 FL	*438.70 FL
6	1		*FRONT RADIATOR GRILLE SPACER	Necessary	45.00 FL	*35.00 FL
7	1		*CENTRE UPPER FINISHER	Not Necessary	450.40 FL	*- FL
8	2		*UPPER FINISHER LH/RH	Not Necessary	57.80 FL	*- FL
9	2		*FRONT FENDER UNDERCOVER LH/RH	Not Necessary	575.80 FL	*- FL
10	2		*FRONT PROTECTOR CORNER PANEL LH/RH	Not Necessary	171.80 FL	*- FL
11	2		*FRONT CORNER PANEL LH/RH	Not Necessary	778.00 FL	*- FL
12	1		*REAR GATE	Repair	1,399.70 FL	*- FL
13	1		*REAR BODY SIDE	Repair	2,600.60 FL	*- FL
14	2		*TAILLAMP LH/RH	Broken/Cut	497.20 FL	*497.20 FL
15	1		*HEATER	Broken	1,800.30 FL	*1,800.30 FL
16	1		*WIPER ARM RH	Scratched	115.20 FL	*115.20 FL
17	1		*SIDE MIRROR SMALL COVER RH	Missing	35.30 FL	*35.30 FL
18	2		*HEADLAMP LH/RH	Cracked	787.20 FL	*787.20 FL
19	1		*REAR REVERSE SENSOR	Broken	295.00 FS	*200.00 FS
20	1		*FRONT LICENSE PLATE	Bent	45.00 FS	*35.00 FS
21	1		*SANKYU STICKER	Necessary	85.60 FS	*85.60 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,736.40</b>	<b>6,427.30</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	3,693.24	1,832.01
<b>Total Parts (\$\$)</b>	<b>9,043.16</b>	<b>4,595.29</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REPAIR & REPLACE PARTS FOR THE AFFECTED AREAS	New	1,200.00	1,000.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	600.00
3	CHECK WIRING,RE-ALIGN TAILLAMPS & ENSURE PROPER FUNCTIONING	New	100.00	30.00
4	REMOVE & REFIT DASHBOARD & RELATED PARTS	New	200.00	150.00
5	REMOVE & REINSTALL 2 PIECES OF BUMPER SENSORS	New	150.00	30.00
6	REMOVE & REPLACE HEATER	New	200.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,050.00</b>	<b>1,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >