5/11/22, 12:01 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20004062/UEA3Q2

11/05/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant Vehicle** GBJ4765Z Insured Vehicle No: SKA9018E No:

Date of Loss: 11/03/2020 Nature of Claim: ΤP Claim No: 4107390041SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBJ4765Z** 

Make & Model: FIAT NEW DOBLO SX, 1.6 MJ E6 GLAZED (A) 263A80008730398 Engine No: Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: ZFA26300006N09839

Colour: Odometer: 9780 km White/Blue

**Engine Capacity:** 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16 Front Left Side: Rear Left Side: Continental 6 mm Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,025.00	450.00	575.00	56.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,300.00	850.00	450.00	34.62
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	2,325.00	1,300.00	1,025.00	44.09

+ Loss of Use (4.0 x S\$60.00/day) (S\$) 240.00 1,540.00 **Liable Amount (50.00%) (S\$)** 770.00 + Doc/Search Fee (S\$) 2.00

> **Nett Liability (S\$)** 772.00 Global Sum Settlement (S\$) 1,150.00

**INSPECTION** 

Date of Assignment: 16/03/2020

Liu's Brother Auto Engineering Worksho Date Inspected: 16/03/2020 Inspected At:

1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL HUB	Repair	225.00 F	*- F
2	1		*CORPORATE ADVERTISEMENT & ARTWORK	Necessary	800.00 FS	*450.00 FS
F=Fra	F=Franchise part. S=SpcNett.					
				Total Parts (S\$)	1,025.00	450.00
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	LABOR FOR PANEL BEATING ,CUT ,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	500.00	350.00		
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	800.00	500.00		
	Gross Labour Cost (S\$)		1,300.00	850.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >