



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2006678
INV Date 28/09/2020
Reference CC4/LPC20004066/Kda3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SKA 5748H
Insured Veh. SJK 4944Z
Claim No. 19/20/20/VP05/023196
Policy No. Z19VP05024954
Accident Date 13/03/2020
Inspection Date 16/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC20004066/Kda3q2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 28-09-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 4944Z	Veh. Inspected	SKA 5748H
	Policy No.	Z19VP05024954	Coverage (\$)	0.00
	Claim No.	19/20/20/VP05/023196	Excess (\$)	0.00
	Assign From	KENNY	Assign Date	16/03/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALLION A1.5 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	NZT2603024175	Colour	METALLIC SILVER
	Odometer	134281	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	MICHELIN	8 mm
	L/H Front Tyre	195/60 R15	MICHELIN	8 mm
	R/H Rear Tyre	195/60 R15	MICHELIN	8 mm
	L/H Rear Tyre	195/60 R15	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/03/2020	Inspection Date	16/03/2020
	Survey held at	D'GARAGE LLP 8 BURN ROAD #09-16 TRIVEX SINGAPORE 369977		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 5748H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	937.80	-
1	REAR BOOT LID CENTRE LOGO	NECESSARY	68.50	68.50
1	REAR BOOT LID LOCK MECHANISM	TO REPAIR SEE LABOUR	272.70	-
1	REAR BOOT LID LOCK STRIKER	TO REPAIR SEE LABOUR	52.50	-
1	REAR BOOT LID WEATHERSTRIP	SERVICEABLE	109.60	-
1	REAR L/H TAIL LAMP	MTG CRACKED	415.90	415.90
1	REAR L/H TAIL LAMP LOWER RETAINER	DISTORTED	67.70	67.70
1	REAR L/H TAIL LAMP BASE PANEL	TO REPAIR SEE LABOUR	133.20	-
1	REAR L/H TAIL LAMP GASKET	NECESSARY	67.30	67.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	677.70	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	493.70	-
1	REAR BUMPER	CRACKED	1,400.00	989.50
2	REAR BUMPER BRACKET	TO REPAIR SEE LABOUR	101.10	-
2	REAR BUMPER REFLECTOR	O/S SERVICEABLE / N/S CRACKED	341.20	170.60
2	REAR BUMPER SIDE RETAINER	N/S DISTORTED	212.80	106.40
1	REAR EXHAUST ASSY	TO REPAIR SEE LABOUR	1,039.40	-
2	REAR EXHAUST MOUNTING	SERVICEABLE	69.90	-
1	REAR BOOT LID "ALLION" EMBLEM (ADDITIONAL)	NECESSARY	58.00	58.00
1	REAR BOOT LID "A15" EMBLEM (ADDITIONAL)	NECESSARY	55.00	55.00
	LESS 25% DISCOUNT		-1,643.50	-499.73
			4,930.50	1,499.17
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	SET REAR L/H TAIL LAMP CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR L/H TAIL LAMP SEALANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CC4/LPC20004066/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR L/H TAIL LAMP BASE PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	DENTED	300.00	200.00
			740.00	250.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR FENDERS AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR BOOT LID LOCK MECHANISM, REAR BOOT LID LOCK STRIKER, REAR L/H TAIL LAMP BASE PANEL, REAR END PANEL, REAR BUMPER BRACKET AND REAR EXHAUST ASSY.		1,200.00	400.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,000.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		80.00	20.00
	TO REMOVE AND INSTALL REAR BOOT LID LOCK MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	350.00	-
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.	NOT NECESSARY	250.00	-
	TO REMOVE AND INSTAILL REAR REVERSE SENSOR.		150.00	50.00
	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOTLID, CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.	NOT NECESSARY	60.00	-
			3,210.00	1,070.00
GRAND TOTAL			8,880.50	2,819.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/LPC20004066/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 5748H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 5748H

RE-INSPECTION

