

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20004067/HPS3Q2**Date:** 03/08/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549		
<b>Claimant Vehicle No :</b>	FBN1758T	<b>Insured Vehicle No :</b>	GBJ6227Y		
Date of Loss:	07/03/2020	Nature of Claim:	TP	Claim No:	MFL2020D0000615

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBN1758T</b>		Engine No:	G3H6E0008158
Make & Model:	YAMAHA NMAX155, 155cc		Chassis No:	MH3SG431000006273
Reg. Date:	27/07/2018 (Man. Year: 2018)		Odometer:	42536 km
Colour:	White			
Engine Capacity:	155 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Michelin 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,587.00	1,414.30	172.70	10.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	665.00	415.00	250.00	37.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,252.00</b>	<b>1,829.30</b>	<b>422.70</b>	<b>18.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	157.64	128.05	29.59	18.77
<b>Nett Amount (S\$)</b>	<b>2,409.64</b>	<b>1,957.35</b>	<b>452.29</b>	<b>18.77</b>
<b>+ Loss of Use (4.0 x S\$20.00/day) (S\$)</b>		80.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,044.80</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,000.00</b>		

INSPECTION

Date of Assignment:	16/03/2020	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	16/03/2020		No. 6 Defu Lane 4
			Singapore 539410
Estimated Period of Repair:	4.0 days		

---

**Adjuster:** LEE HOCK ANN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Jul 2020)	
<b>Parts:</b>	N/A	YAMAHA NMAX155 155cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBN1758T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Scratched	34.00 F	*34.00 FL
2	1		*BOARD FOOTREST LH	Scratched	52.00 F	*52.00 FL
3	1		*BOARD FOOTREST RH	Scratched	52.00 F	*52.00 FL
4	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Scratched	222.00 F	*222.00 FL
5	1		*BRACKET BOX REAR (GIVI)	Bent	62.00 F	*62.00 FL
6	1		*COVER CLUTCH OUTER	Scratched	28.00 F	*28.00 FL
7	1		*COVER RADIATOR	Scratched	12.00 F	*12.00 FL
8	1		*COVER SIDE CENTRE RH (WHITE)	Scratched	30.00 F	*30.00 FL
9	1		*COVER SIDE REAR LH (WHITE)	Scratched	40.00 F	*40.00 FL
10	1		*COVER SIDE REAR RH (WHITE)	Scratched	40.00 F	*40.00 FL
11	1		*ENGINE BRACKET COMP	Bent	70.00 F	*70.00 FL
12	1		*LAMP SIGNAL FRONT LH	Scratched	35.00 F	*35.00 FL
13	1		*LEVER BRACKET LH	Crumpled	18.00 F	*18.00 FL
14	1		*LEVER BRACKET RH	Crumpled	18.00 F	*18.00 FL
15	1		*MUDGUARD FRONT (WHITE)	Scratched	52.00 F	*52.00 FL
16	1		*MUDGUARD REAR	Scratched	47.00 F	*47.00 FL
17	1		*PIPE EXHAUST ASSY	Bent	407.00 F	*407.00 FL
18	1		*PROTECTOR EXHAUST	Crumpled	38.00 F	*38.00 FL
19	7		*RIVET	Necessary	14.00 F	*14.00 FL
20	1		*SHAFT PIVOT	Serviceable	12.00 F	*- FL
21	1		*STAND MAIN	Scratched	66.00 F	*66.00 FL
22	1		*STOPPER MAINSTAND	Serviceable	17.00 F	*- FL
23	1		*STOPPER ,MAIN STAND	Serviceable	7.00 F	*- FL
24	1		*COVER SIDE CENTRE LH (WHITE)	Scratched	30.00 F	*30.00 FL
25	1		*STICKER (CERTIS CISCO) SIDE REAR RH NEW MODEL	Necessary	44.00 FS	*44.00 FS
26	2		*STICKER (CERTIS CISCO) NEW LOGO	Necessary	88.00 FS	*88.00 FS
27	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	37.00 FS	*37.00 FS
28	1		*STICKER (CISCO) SIDE REAR LH NEW MODEL	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,587.00</b>	<b>1,551.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	136.70
<b>Total Parts (\$\$)</b>	<b>1,587.00</b>	<b>1,414.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	378.00	260.00
2	SPRAY PAINT COVER SIDE REAR LH (LACQUER)	New	63.00	45.00
3	SPRAY PAINT COVER SIDE REAR RH (LACQUER)	New	63.00	45.00
4	SPRAY PAINT MUDGUARD FRONT (LACQUER)	New	49.00	30.00
5	TRANSPORT CHARGES -FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO BASE ONCE REPAIR DONE	New	112.00	35.00
<b>Gross Labour Cost (\$\$)</b>			<b>665.00</b>	<b>415.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >