

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004069/KPS3Q2
Date: 18/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800138382
Claimant Vehicle No :	SKC2355S	Insured Vehicle No :	SMF7318C
Date of Loss:	08/03/2020	Nature of Claim:	TP
		Claim No:	6572608858SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC2355S		
Make & Model:	BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)	Engine No:	09997626N52B30AF
Reg. Date:	24/02/2011 (Man. Year: 2010)	Chassis No:	WBAKB22040CN74771
Colour:	Metallic Black	Odometer:	147772 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,249.95	1,681.50	1,568.45	48.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	550.00	150.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,949.95	2,231.50	1,718.45	43.51
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	3,949.95	2,250.00	1,699.95	43.04
+ GST 7.00/7.00% (S\$)	276.50	157.50	119.00	43.04
Nett Amount (S\$)	4,226.45	2,407.50	1,818.95	43.04
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		2,629.50		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment:	17/03/2020		
Date Inspected:	17/03/2020	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Buckled	1,770.00 FL	*1,770.00 FL	
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	710.00 FL	*- FL	
3	1		*REAR BUMPER LOWER SKIRT	Not Necessary	285.00 FL	*- FL	
4	2		*REVERSE SENSORS	Not Necessary	656.00 FL	*- FL	
					Sub Total (\$)	3,421.00	1,770.00
					- List Item Discount on L Items 5.00/5.00% (\$)	171.05	88.50
					Total Parts (\$)	3,249.95	1,681.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,REVERSE SENSOR ,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME	New	350.00	250.00
2	PUTTY & RESPRAY ON REAR BUMPER ,REAR PANEL	New	350.00	300.00
			Gross Labour Cost (S\$)	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >