

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2020 Edit Reg		13 Mar 2020 00:00 Edit Adj Rpt	S\$7,800.00 Edit Estimates	S\$7,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LUZERNE PTE LTD , Co. Reg. No.: 197701904H									
Main Claimant: VIKING LEASING									
Vehicle Reg. No.: SJQ1487P		Date of Loss: 11/03/2020 17:00 - :59 [130 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4302486782SG		Policy/Cover Note No.: 1800133231 (Comprehensive)							
Vehicle Reg. No. (Insured): GBH9262K		Policy No. (Claimant):							
		Excess:							
Repairer: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road, 159143 Leng Kee - Tel: 64721313									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/03/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (04/08/2020): Alert - Adj Mandate Approved (S\$9468.00) - SJQ1487P - Claim Handler: Lee, Ming-Y... - AIG_SG (18/03/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJQ1487P (4302486782SG)**
[GBH9262K]

TP
VIKING LEASING
Mar 11 2020 5:00PM
[LUZERNE PTE LTD]
Optima Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/03/20 11:38	Video - Accident	Load MP4	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/07/20 14:58	General View	Load JPG	☒
2	27/07/20 14:58	General View	Load JPG	☒
3	27/07/20 14:58	General View	Load JPG	☒
4	27/07/20 14:58	General View	Load JPG	☒
5	27/07/20 14:58	General View	Load JPG	☒
6	27/07/20 14:58	General View	Load JPG	☒
7	27/07/20 14:58	General View	Load JPG	☒
8	27/07/20 14:58	General View	Load JPG	☒
9	27/07/20 14:58	General View	Load JPG	☒
10	27/07/20 14:58	General View	Load JPG	☒
11	27/07/20 14:58	General View	Load JPG	☒
12	27/07/20 14:58	General View	Load JPG	☒
13	27/07/20 14:58	General View	Load JPG	☒
14	27/07/20 14:58	General View	Load JPG	☒
15	27/07/20 14:58	General View	Load JPG	☒
16	27/07/20 14:58	General View	Load JPG	☒
17	27/07/20 14:58	General View	Load JPG	☒
18	27/07/20 14:58	General View	Load JPG	☒
19	27/07/20 14:58	General View	Load JPG	☒
20	27/07/20 14:58	General View	Load JPG	☒
21	27/07/20 14:58	General View	Load JPG	☒
22	27/07/20 14:58	General View	Load JPG	☒
23	27/07/20 14:58	General View	Load JPG	☒
24	27/07/20 14:58	General View	Load JPG	☒
25	27/07/20 14:58	General View	Load JPG	☒
26	27/07/20 14:58	General View	Load JPG	☒
27	27/07/20 14:58	General View	Load JPG	☒
28	27/07/20 14:58	General View	Load JPG	☒
29	27/07/20 14:58	General View	Load JPG	☒
30	27/07/20 14:58	General View	Load JPG	☒
31	27/07/20 14:58	General View	Load JPG	☒
32	27/07/20 14:58	General View	Load JPG	☒
33	27/07/20 14:58	General View	Load JPG	☒
34	27/07/20 14:58	General View	Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
35	27/07/20 14:58	General View		Load JPG	☒
36	27/07/20 14:58	Odometer Reading		Load JPG	☒
37	27/07/20 14:58	Chassis Number		Load JPG	☒
38	27/07/20 14:59	Reinspection Photo		Load JPG	☒
39	27/07/20 14:59	Reinspection Photo		Load JPG	☒
40	27/07/20 14:59	Reinspection Photo		Load JPG	☒
41	27/07/20 14:59	Reinspection Photo		Load JPG	☒
42	27/07/20 14:59	Reinspection Photo		Load JPG	☒
43	27/07/20 14:59	Reinspection Photo		Load JPG	☒
44	27/07/20 14:59	Reinspection Photo		Load JPG	☒
45	27/07/20 14:59	Reinspection Photo		Load JPG	☒
46	27/07/20 14:59	Reinspection Photo		Load JPG	☒
47	27/07/20 14:59	Reinspection Photo		Load JPG	☒
48	27/07/20 14:59	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/03/20 16:55	TP GIA REPORT		Load PDF	
2	27/07/20 10:52	LETTER TO OI		Load PDF	
3	27/07/20 15:16	LOD		Load PDF	
4	27/07/20 15:16	GIA SEARCH FEE		Load PDF	
5	27/07/20 15:16	TOWING		Load PDF	
6	18/08/20 13:18	Authorisation to Act		Load PDF	
7	18/08/20 13:18	Release Voucher		Load PDF	
8	18/08/20 13:18	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/03/20 11:37	OI GIA REPORT		Load PDF	
2	18/03/20 11:37	OI GIA REPORT - Amended		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBH9262K (Insd veh)	Model:	TOYOTA COROLLA ALTIS 1.6
	SJQ1487P (TP veh)		(A)
Date of Accident:	11/03/2020		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No	
Repair Estimate	:	\$				14,803.18
Final Repair Cost	:	\$				9,460.00
Loss of Use	:	\$				14.00 days at \$100.00 per day
Rental (if any)	:	\$				days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				9,460.00

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability ____ 100 ____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: ____				
BOLA Liability: ____ (%)				Assessed Liability (*): ____ 28 ____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	: \$	9,460.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

18 Aug
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20004071/KDS3S2**Date:** 19/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800133231
Claimant Vehicle No :	SJQ1487P	Insured Vehicle No :	GBH9262K
Date of Loss:	11/03/2020	Nature of Claim:	TP
		Claim No:	4302486782SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ1487P	Engine No:	3ZZ4880291
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106143300
Reg. Date:	27/04/2009 (Man. Year: 2009)	Odometer:	214179 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	KAPSEN 8 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	KAPSEN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,114.75	6,712.12	3,402.63	33.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	3,190.00	530.00	14.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,834.75	9,902.12	3,932.63	28.43
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	13,834.75	7,800.00	6,034.75	43.62
+ GST 7.00/7.00% (S\$)	968.43	546.00	422.43	43.62
Nett Amount (S\$)	14,803.18	8,346.00	6,457.18	43.62
+ Loss of Use (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		9,798.00		
Global Sum Settlement (S\$)		9,460.00		

INSPECTION

Date of Assignment:	13/03/2020		
Date Inspected:	13/03/2020	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	12.0 days		

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Buckled / Cracked	650.50 FL	*486.50 FL
2	1	*FRONT BUMPER REINFORCEMENT	Bent	419.50 FL	*315.00 FL
3	8	*FRONT BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
4	1	*FRONT BUMPER SIDE BRACKET LH	Distorted	59.20 FL	*59.20 FL
5	1	*FRONT BUMPER SIDE BRACKET RH	Distorted	59.20 FL	*59.20 FL
6	1	*FRONT GRILLE ASSY	Dented / Distorted	328.30 FL	*265.10 FL
7	1	*FRONT GRILLE EMBLEM	Necessary	55.30 FL	*55.30 FL
8	6	*FRONT GRILLE CLIPS	Necessary	37.20 FL	*37.20 FL
9	1	*FRONT HEADLAMP LH	Mtg Cracked	657.90 FL	*583.60 FL
10	1	*FRONT HEADLAMP RH	Mtg Cracked	657.90 FL	*583.60 FL
11	1	*FRONT SUPPORT PANEL ASSY	Repair	764.10 FL	*- FL
12	1	*FRONT BONNET LOCK	Distorted	94.30 FL	*94.30 FL
13	1	*FRONT BONNET LOCK STAY PANEL	Bent	121.60 FL	*121.60 FL
14	1	*FRONT AIRCON CONDENSOR	Bent / Punctured	1,121.70 FL	*1,121.70 FL
15	1	*FRONT RADIATOR	Serviceable	1,680.50 FL	*- FL
16	1	*REAR BOOT LID	Bent	859.70 FL	*794.40 FL
17	1	*REAR BOOT LID EMBLEM	Necessary	46.40 FL	*46.40 FL
18	1	*REAR BOOT LID 1.6 EMBLEM	Necessary	42.60 FL	*42.60 FL
19	1	*REAR BOOT LID COROLLA EMBLEM	Necessary	47.60 FL	*47.60 FL
20	1	*REAR BOOT LID ALTIS EMBLEM	Necessary	48.80 FL	*48.80 FL
21	1	*REAR BOOT LID CHROME GARNISH	Cracked	437.80 FL	*203.20 FL
22	1	*REAR BOOT LID INNER LOCK	Dented	144.70 FL	*144.70 FL
23	1	*REAR BOOT LID BACK UP LAMP LH	Cracked	218.10 FL	*218.10 FL
24	1	*REAR BOOT LID BACK UP LAMP RH	Cracked	218.10 FL	*218.10 FL
25	1	*REAR END PANEL	Bent	793.60 FL	*691.40 FL
26	1	*REAR END PANEL UPPER COVERING	Distorted	194.10 FL	*194.10 FL
27	1	*REAR SPARE TYRE PANEL UPPER BOARD	Cracked	297.90 FL	*276.60 FL
28	1	*REAR BOOT HINGE LH	Repair	78.90 FL	*- FL
29	1	*REAR BOOT HINGE RH	Repair	78.90 FL	*- FL
30	1	*REAR BUMPER	Bent	735.20 FL	*561.40 FL
31	1	*REAR BUMPER IMPACT ABSORBER	Cracked	152.60 FL	*152.60 FL
32	1	*REAR BUMPER SIDE BRACKET LH	Bent	93.90 FL	*93.90 FL
33	1	*REAR BUMPER SIDE BRACKET RH	Bent	93.90 FL	*93.90 FL
34	1	*REAR BUMPER REINFORCEMENT SUPPORT BRACKET RH	Repair	51.30 FL	*- FL
35	8	*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
36	1	*REAR TAIL LAMP LH	Cracked	566.30 FL	*342.00 FL
37	1	*REAR TAIL LAMP RH	Cracked	566.30 FL	*342.00 FL
38	1	*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
39	1	*REAR TAIL LAMP RH (NPA)	Repair	0.00 FL	*- FL
40	1	*REAR QUARTER PANEL LH (NPA)	Repair	0.00 FL	*- FL
41	1	*REAR QUARTER PANEL RH (NPA)	Repair	0.00 FL	*- FL
42	1	*REAR BOOT LID RUBBER (@ \$231.10 DISC 50%)	Dented / Cut	173.33 FS	*115.55 FS
43	1	*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
44	1	*FRONT NUMBER PLATE HOLDER	Dented	40.00 FS	*40.00 FS
45	1	*FRONT RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
46	1	*REAR BUMPER REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
47	1	*REAR END PANEL JOINT SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,255.23 8,807.65
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,140.48 2,095.53

Total Parts (\$\$) 10,114.75 6,712.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.	New	1,300.00	1,200.00
2	LABOUR CHARGES FOR PAINTING & TO TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT SUPPORT PANEL, REAR BOOT LID, REAR END PANEL, REAR TAIL LAMP PANEL LH, REAR TAIL LAMP RH, REAR QUARTER PANEL LH, REAR QUARTER PANEL RH && ETC.	New	2,200.00	1,800.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	New	60.00	50.00
4	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEMS.	New	60.00	40.00
5	TO REFILL AIR CON GAS & VACUUM.	New	100.00	100.00
Gross Labour Cost (\$)			3,720.00	3,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >