

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004082/EEA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425523

Claimant
Vehicle No : SMH4909G **Insured Vehicle No :** SGF9688S

Date of Loss: 14/03/2020 Nature of Claim: TP Claim No: 3538170620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No: | SMH4909G | Engine No: | CHZA93018 |
| Make & Model: | AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) | Chassis No: | WAUZZZGA0KA000767 |
| Reg. Date: | 24/01/2019 (Man. Year: 2018) | Odometer: | 22387 km |
| Colour: | Red | | |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 215/60R16 | Rear Tyre Size: | 215/60R16 |
| Front Left Side: | Bridgestone 5 mm | Rear Left Side: | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,906.00 | 1,356.40 | 1,549.60 | 53.32 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,072.00 | 1,522.00 | 2,550.00 | 62.62 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 6,978.00 | 2,878.40 | 4,099.60 | 58.75 |
| + GST 7.00/7.00% (\$\$) | 488.46 | 201.49 | 286.97 | 58.75 |
| Nett Amount (\$\$) | 7,466.46 | 3,079.89 | 4,386.57 | 58.75 |
| + Loss of Use (3.0 x S\$60.00/day) (\$\$) | | 180.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 3,261.89 | | |

INSPECTION

Date of Assignment: 19/03/2020

Date Inspected: 19/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|--------------------------------------|---------------|-----------------|-----------------|
| 1 | 1 | | *REAR BUMPER | Dented | 1,108.00 FS | *886.40 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 73.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER SPOILER | Cut | 268.00 FS | *214.00 FS |
| 4 | 1 | | *REAR BUMPER TOWING EYE COVER | Not Necessary | 41.00 FS | *- FS |
| 5 | 2 | | *REAR LIGHT REFLECTOR-LH/RH | Not Necessary | 56.00 FS | *- FS |
| 6 | 1 | | *REAR BUMPER CARRIER | Not Necessary | 517.00 FS | *- FS |
| 7 | 2 | | *REAR BUMPER HOLDING STRAP-LH/RH | Not Necessary | 24.00 FS | *- FS |
| 8 | 1 | | *REAR PARKING AID SENSOR-INNER (NPA) | Not Necessary | 0.00 FS | *- FS |
| 9 | 4 | | *REAR PARKING AID SEAL RING | Not Necessary | 14.00 FS | *- FS |
| 10 | 1 | | *PACKING ADHESIVE | Not Necessary | 18.00 FS | *- FS |
| 11 | 1 | | *AUDI EMBLEM | Not Necessary | 117.00 FS | *- FS |
| 12 | 1 | | *Q2 INSCRIPTION | Not Necessary | 90.00 FS | *- FS |
| 13 | 2 | | *REAR WHEEL COVER-LH/RH | Necessary | 320.00 FS | *256.00 FS |
| 14 | 1 | | *REAR NO PLATE | Not Necessary | 60.00 FS | *- FS |
| 15 | 1 | | *SUNDRIES | Not Necessary | 200.00 FS | *- FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (\$\$) | | | | | 2,906.00 | 1,356.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 280.00 | 280.00 |
| 2 | TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 1,600.00 | 500.00 |
| 3 | TO RESPRAY REAR BUMPER AND REAR LID | New | 2,000.00 | 550.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 4,072.00 | 1,522.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >