

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004090/ADA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100471366-03

Claimant
Vehicle No : SKZ8378R **Insured Vehicle No :** SDF9168L

Date of Loss: 13/03/2020 Nature of Claim: TP Claim No: 1996680609SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8378R		
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Engine No:	LEB5061941
Reg. Date:	04/02/2016 (Man. Year: 2015)	Chassis No:	RU31111933
Colour:	Black	Odometer:	60129 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,356.80	3,014.16	3,342.64	52.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	860.00	800.00	48.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,016.80	3,874.16	4,142.64	51.67
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	8,016.80	3,100.00	4,916.80	61.33
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,607.45		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020 Inspected At:

 Fong Motors (HQ)
 1 Kaki Bukit Ave 6 #01-45, Autobay@
 Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	869.20 F	*869.20 FL
2	1		*FRONT BUMPER SIDE RETAINER	Necessary	45.80 F	*45.80 FL
3	1		*FRONT BUMPER SIDE BRACKET	Cracked	39.80 F	*39.80 FL
4	1		*BUMPER REINFORCEMENT	Not Necessary	368.00 F	*- FL
5	1		*FRONT RH/LH HEAD LAMP	N/s Cracked	3,847.00 F	*1,923.50 FL
6	1		*FRONT RH/LH HEAD LAMP LOWER BRACKET	N/s Cracked	79.80 F	*39.90 FL
7	1		*RADIATOR GRILLE UPPER	Cracked	385.00 F	*385.00 FL
8	1		*RADIATOR GRILLE EMBLEM	Necessary	39.50 F	*39.50 FL
9	1		*RADIATOR GRILLE CHROME	Cracked	395.00 F	*395.00 FL
10	1		*RADIATOR GRILL BASE	Not Necessary	191.90 F	*- FL
11	1		*FENDER EMBLEM-HYBRID	Not Necessary	45.80 F	*- FL
12	1		*FRONT BUMPER CLIP	Necessary	50.00 F	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,356.80	3,767.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	753.54
Total Parts (\$\$)	6,356.80	3,014.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK AND CHANGE PARTS	New	700.00	400.00
2	TO SPRAY BONNET,FENDER AND BUMPER	New	800.00	400.00
3	TUFF KOTE	New	80.00	30.00
4	TO CHECK WIRING	New	80.00	30.00
Gross Labour Cost (\$\$)			1,660.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >