

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 1056U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	1,980.00	1,795.00
2	FRONT BUMPER RETAINERS	O/S DISTORTED	110.00	55.00
2	FRONT BUMPER BRACKETS	TO REPAIR SEE LABOUR	140.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT FENDER RH	BENT	760.00	760.00
1	FRONT FENDER INNER SHIELD RH	CRACKED	230.00	230.00
1	FRONT FENDER REFLECTOR RH	SERVICEABLE	92.00	-
1	FRONT LOWER ARM RH	DISTORTED	470.00	470.00
1	FRONT SHOCK ABSORBER RH	BENT	390.00	390.00
1	FRONT KNUCKLE ARM RH	BENT	560.00	510.00
1	FRONT KNUCKLE ARM BEARING RH	NECESSARY	310.00	310.00
1	FRONT WHEEL RIM RH	DENTED	590.00	590.00
	LESS 10% DISCOUNT		-	-515.00
			5,672.00	4,635.00
	LABOUR			
	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKETS.		800.00	400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		700.00	400.00
	TO REMOVE, REPLACE FRONT FENDER FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE, REPLACE FRONT KNUCKLE ARM, SHOCK ABSORBER AND LOWER ARM.		350.00	200.00
	TO REMOVE, REPLACE FRONT TYRE AND WHEEL RIM.		100.00	20.00
	TO CHECK WIRING AND LIGHTINGS.		80.00	20.00
			2,330.00	1,040.00
	GRAND TOTAL		8,002.00	5,675.00

Report Ref No. CS/LPC20004103/Kqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/LPC20004103/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser