

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20004108/EGA3Q2

**Date:** 06/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHB3580S	<b>Insured Vehicle No :</b>	SHC8573A
Date of Loss: 12/03/2020	Nature of Claim: TP	Claim No: MCT20030328

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3580S	Engine No:	D4DFDU529352
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMFU069310
Reg. Date:	01/01/2000 (Man. Year: 1900)	Odometer:	765085 km
Colour:	Yellow		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R15	Rear Tyre Size:	205/60R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,753.10	1,990.18	2,762.92	58.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,300.00	970.00	42.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,023.10</b>	<b>3,290.18</b>	<b>3,732.92</b>	<b>53.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>		
<b>(S\$)</b>	7,023.10	2,650.00	4,373.10	62.27
<b>+ GST 7.00/7.00% (S\$)</b>	491.62	185.50	306.12	62.27
<b>Nett Amount (S\$)</b>	<b>7,514.72</b>	<b>2,835.50</b>	<b>4,679.22</b>	<b>62.27</b>
<b>+ Loss of Use (6.0 x S\$40.00/day) (S\$)</b>		240.00		
<b>+ Car Rental (6.0 x S\$103.43/day) (S\$)</b>		620.58		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,703.53</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,700.00</b>		

### INSPECTION

Date of Assignment: 17/03/2020

Date Inspected: 17/03/2020 Inspected At:

Ding Automotive Pte Ltd (SIN MING)  
BLK 10 #01-20 SIN MING, IND EST  
SEC C  
Singapore 575645

Estimated Period of Repair: 4.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB3580S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LHS DOOR	Dented	2,201.43 FL	*2,201.43 FL
2	1		*REAR BUMPER	Repair	599.60 FL	*- FL
3	1		*REAR LHS FENDER	Repair	2,210.30 FL	*- FL
4	1		*REAR LHS WHEEL CAP	Cut	186.30 FL	*186.30 FL
5	1		*LHS SIDE SKIRT (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR LHS DOOR STICKER -BOOK NOW COMFORT DELGRO GOOGLE PLAY APPS STORE	Necessary	150.00 FS	*80.00 FS
7	1		*REAR BUMPER CLIPS	Not Necessary	45.00 FS	*- FS
8	1		*REAR LHS FENDER SEALANT	Not Necessary	100.00 FS	*- FS
9	1		*WINDSCREEN DAMPER	Not Necessary	100.00 FS	*- FS
10	1		*WINDSCREEN PRIMER	Not Necessary	100.00 FS	*- FS
11	1		*WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,792.63</b>	<b>2,467.73</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,039.53	477.55
<b>Total Parts (\$\$)</b>	<b>4,753.10</b>	<b>1,990.18</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	800.00	500.00
2	RESPRAY REAR BUMPER	New	250.00	200.00
3	RESPRAY REAR LHS FENDER	New	250.00	200.00
4	RESPRAY REAR LHS DOOR	New	250.00	200.00
5	R&R REAR WINDSCREEN TO REPLACE FENDER	New	200.00	0.00
6	R&R REAR PASSENGER SEAT ,SEAT BELT ,BOOT COMPARTMENT TRIM COVERS ,REAR LHS QUARTER GLASS TO REPLACE REAR LHS FENDER	New	200.00	0.00
7	RUST PROOFING	New	120.00	0.00
8	RESPRAY LHS SIDE SKIRT	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,270.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >