

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/III20004109/KPA3Q2

Date:

19/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SHB9988K**Insured Vehicle No :**

SH8773H

Date of Loss: 11/03/2020

Nature of Claim:

TP

Claim No:

MCT20030195

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB9988K**

Make & Model: TOYOTA ALPHARD, 2.5 X CVT (A)

Engine No: 2AR2222555

Reg. Date: 22/11/2019 (Man. Year: 2019)

Chassis No: AYH300090081

Colour: Metallic Pearl White

Odometer: 29836 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,774.90	3,834.42	4,940.48	56.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,080.00	1,680.00	16,400.00	90.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,854.90	5,514.42	21,340.48	79.47
+ GST 7.00/7.00% (S\$)	1,879.84	386.01	1,493.83	79.47

Nett Amount (S\$)	28,734.74	5,900.43	22,834.31	79.47
+ Car Rental (9.0 x S\$159.43/day) (S\$)		1,434.87		
Nett Liability (S\$)		7,335.30		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 16/03/2020

Date Inspected: 16/03/2020

Estimated Period of Repair: 5.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio St 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2021)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB9988K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	2,078.20 FL	*2,078.20 FL
2	1		*REAR END PANEL	Serviceable	781.70 FL	*- FL
3	1		*TAILGATE	Bent	2,040.50 FL	*2,040.50 FL
4	1		*SUPPORT ,REAR BUMPER SIDE ,RH	Serviceable	240.00 FL	*- FL
5	1		*SUPPORT ,REAR BUMPER SIDE ,LH	Serviceable	240.00 FL	*- FL
6	1		*SET PARKING AID	Scratched	4,000.00 FS	*500.00 FS
7	1		*SET PARKING AID ,SENSOR RETAINER	Serviceable	356.00 FS	*- FS
8	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*80.00 FS
9	1		*SET REAR LH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
10	1		*SET REAR RH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
11	1		*PLATE ,BACK DOOR -ALPHARD	Necessary	52.00 FS	*52.00 FS
12	1		*PLATE ,BACK DOOR -E-LPHARD	Necessary	41.00 FS	*41.00 FS
13	1		*EMBLEM SUB-ASSY	Necessary	72.40 FS	*72.40 FS
14	1		*PLATE BACK DOOR -TOYOTA LOGO	Not Necessary	68.20 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,120.00	4,864.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,345.10	1,029.68
Total Parts (\$\$)	8,774.90	3,834.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	7,500.00	700.00
3	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
5	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
13	TO INSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
15	TOWING FEES	New	180.00	0.00
16	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
Gross Labour Cost (\$\$)			18,080.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >