

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20004141/KBS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800039355
Claimant Vehicle No :	SHB9911G	Insured Vehicle No :	SJN7078M
Date of Loss:	05/03/2020	Nature of Claim:	TP
		Claim No:	3640911758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9911G	Engine No:	2AR2298371
Make & Model:	TOYOTA ALPHARD, 2.5 SC CVT (A)	Chassis No:	AYH300095317
Reg. Date:	17/01/2020 (Man. Year: 2019)	Odometer:	12372 km
Colour:	Metallic Pearl White		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,774.91	3,334.43	5,440.48	62.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,080.00	1,480.00	16,600.00	91.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,854.91	4,814.43	22,040.48	82.07
+ GST 7.00/7.00% (S\$)	1,879.84	337.01	1,542.83	82.07

Nett Amount (S\$)	28,734.75	5,151.44	23,583.31	82.07
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$159.43/day) (S\$)		1,434.87		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,043.76		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 10/03/2020

Date Inspected: 10/03/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	2,078.20 FL	*2,078.20 FL
2	1		*REAR END PANEL	Repair	781.70 FL	*- FL
3	1		*TAILGATE	Bent	2,040.50 FL	*2,040.50 FL
4	1		*SUPPORT ,REAR BUMPER SIDE ,RH	Serviceable	240.00 FL	*- FL
5	1		*SUPPORT ,REAR BUMPER SIDE ,LH	Serviceable	240.00 FL	*- FL
6	1		*SET PARKING AID	Not Necessary	4,000.00 FS	*- FS
7	1		*SET PARKING AID ,SENSOR RETAINER	Serviceable	356.00 FS	*- FS
8	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*80.00 FS
9	1		*SET REAR LH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
10	1		*SET REAR RH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
11	1		*PLATE ,BACK DOOR ,ALPHARD	Necessary	52.00 FS	*52.00 FS
12	1		*PLATE ,BACK DOOR ,E-FOUR	Necessary	41.00 FS	*41.00 FS
13	1		*EMBLEM SUB-ASSY	Necessary	72.41 FS	*72.41 FS
14	1		*PLATE ,BACK DOOR ,TOYOTA LOGO	Not Necessary	68.20 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,120.01	4,364.11
- List Item Discount on L Items 25.00/25.00% (S\$)	1,345.10	1,029.68
Total Parts (S\$)	8,774.91	3,334.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	7,500.00	500.00
3	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR }	New	380.00	60.00
5	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST }	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
15	TOWING FEES	New	180.00	0.00
16	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
			Gross Labour Cost (\$\$)	18,080.00
				1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >