Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/AIG20004143/GBA3Q2 Our File No:

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100364939 Claimant GV6622S Insured Vehicle No: SKN136M

Vehicle No:

Date of Loss: 12/03/2020 Nature of Claim: TP Claim No: 1687055009SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

GV6622S Reg No:

Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KE628D623006 Reg. Date: 23/11/2018 (Man. Year: 2018) Chassis No: VSKYBAM20Z0172998

Colour: Silver Odometer: 39990 km

Engine Capacity: 1461 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,169.70	872.55	2,297.15	72.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	670.00	900.00	57.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,739.70	1,542.55	3,197.15	67.45
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	4,739.70	1,200.00	3,539.70	74.68
+ GST 7.00/7.00% (S\$)	331.78	84.00	247.78	74.68
Nett Amount (S\$)	5,071.48	1,284.00	3,787.48	74.68
+ Loss of Use (4.0 x S\$1	00.00/day) (S\$)	400.00		
+ Doc/Search Fee (S\$)		29.00		
Ne	ett Liability (S\$)	1,713.00		
Global Sum S	Settlement (S\$)	1,700.00		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020 Inspected At: REVO PERFORMANCE PTE LTD

1 KAKI BUKIT AVE 6 #02-51

Singapore 417883

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount			
1	1		*REAR TAIL LAMP RIGHT HAND	Scratched	232.10 F	*232.10 FL			
2	1		*REAR FENDER RIGHT HAND	Repair	1,791.60 F	*- FL			
3	1		*REAR BUMPER	Cracked	593.20 F	*593.20 FL			
4	1		*REAR BUMPER SIDE RETAINER RIGHT HAND	Deformed	60.20 F	*60.20 FL			
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	346.20 F	*- FL			
6	1		*REAR BUMPER INNER SPONGE	Cracked	146.40 F	*84.00 FL			
F=Fra	F=Franchise part. L=ListItemDisc.								
				Sub Total (S\$)	3,169.70	969.50			
- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	96.95				
				Total Parts (S\$)	3,169.70	872.55			
	Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	850.00	400.00
2	CHECK WIRING	New	60.00	30.00
3	RUST PROOFING	New	60.00	0.00
4	SPRAY PAINTING	New	520.00	200.00
5	TO REMOVE & REFIT BUMPER SENSOR	New	80.00	40.00
		Gross Labour Cost (S\$)	1,570.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >