

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004147/KGA3Q2
Date: 27/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900105863
Claimant Vehicle No :	SKJ8406C	Insured Vehicle No :	SLP3091R
Date of Loss:	13/03/2020	Nature of Claim:	TP
		Claim No:	4338468098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ8406C	Engine No:	1ZRX256943
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104156373
Reg. Date:	17/05/2013 (Man. Year: 2013)	Odometer:	98354 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,302.62	2,053.12	1,249.50	37.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,710.00	1,020.00	37.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,032.62	3,763.12	2,269.50	37.62
Approved Total (Overridden) (S\$)		3,000.00		

(S\$)	6,032.62	3,000.00	3,032.62	50.27
+ GST 7.00/7.00% (S\$)	422.28	210.00	212.28	50.27
Nett Amount (S\$)	6,454.90	3,210.00	3,244.90	50.27
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,854.00		

INSPECTION

Date of Assignment: 17/03/2020

Date Inspected: 17/03/2020

Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented / Warped	1,135.00 FL	*1,135.00 FL
2	1		*REAR DOOR PROTECTOR	Dented	362.00 FL	*362.00 FL
3	1		*REAR DOOR PROTECTOR MOULDING	Necessary	125.00 FL	*125.00 FL
4	10		*REAR DOOR TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
5	1		*FRONT DOOR	Repair	1,176.00 FL	*- FL
6	1		*FRONT DOOR PROTECTOR	Dented	357.00 FL	*357.00 FL
7	1		*FRONT DOOR PROTECTOR MOULDING	Necessary	125.00 FL	*125.00 FL
8	10		*FRONT DOOR TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
9	1		*REAR BUMPER	Cracked	512.00 FL	*512.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	1		*REAR BUMPER CORNER RETAINER LH	Distorted	71.50 FL	*71.50 FL
12	1		*REAR DOOR INNER INSULATION	Not Necessary	150.00 FS	*- FS
13	1		*FRONT DOOR INNER INSULATION	Not Necessary	150.00 FS	*- FS
					Sub Total (\$\$)	4,303.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,000.88
					Total Parts (\$\$)	3,302.62
						2,737.50
						684.38
						2,053.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REFIT DOOR FITTINGS /ANCILLARY ACCESSORIES X2	New	300.00	60.00
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	100.00	30.00
3	TO REPAIR/ RESPRAY REAR WHEEL RIM	New	150.00	60.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	LABOUR CHARGE- PANEL BEATING ,REPAIRING OF FRONT RH FENDER ,DOOR B PILLAR ,REAR FENDER ,LOWER PANEL AND PARTS REPLACEMENT	New	700.00	500.00
6	TO RESPRAY AFFECTED AREAS	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			2,730.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >