

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20004148/QVF3E2

Date: 22/05/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30625919011
Claimant Vehicle No :	SLK8709L	Insured Vehicle No :	GBE2278C
Date of Loss:	12/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8709L	Engine No:	L15B4406107
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11206107
Reg. Date:	02/02/2017 (Man. Year: 2016)	Odometer:	250471 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,760.48	1,619.04	5,141.44	76.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,040.00	1,200.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,000.48	2,659.04	6,341.44	70.46
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	9,000.48	2,100.00	6,900.48	76.67
+ GST 7.00/7.00% (S\$)	630.03	147.00	483.03	76.67
Nett Amount (S\$)	9,630.51	2,247.00	7,383.51	76.67

INSPECTION

Date of Assignment:	20/05/2020	
Date Inspected:	18/03/2020 Inspected At:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-01 Carros Centre Singapore 737869
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)	
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLK8709L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*980.00 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL
4	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*120.00 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	155.00 FL	*- FL
6	1		*REAR TAILGATE LOCK	Serviceable	550.00 FL	*- FL
7	1		*REAR TAILGATE LOCK CATCH	Serviceable	180.00 FL	*- FL
8	1		*REAR END PANEL	Repair	830.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	155.00 FL	*- FL
10	1		*REAR BUMPER	Crumpled	955.00 FL	*762.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
12	1		*SET END PANEL TOP GARNISH CLIPS	Serviceable	80.00 FS	*- FS
13	1		*REVERSE SENSOR	Serviceable	490.00 FS	*- FS
14	1		*SET BODY SEALANT	Serviceable	300.00 FS	*- FS
15	1		*WINDSCREEN SEALANT	Necessary	2,100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,688.10	2,008.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	927.62	389.76
Total Parts (\$\$)	6,760.48	1,619.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR END PANEL, REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY REAR TAILGATE, END PANEL AND SPARE TYRE PANEL	New	900.00	400.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	0.00
5	TO CHECK WIRING SYSTEM	New	100.00	20.00
Gross Labour Cost (S\$)			2,240.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >