

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20004157/AEA3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900165440

**Claimant**  
**Vehicle No :** SGY7740L **Insured Vehicle No :** SKM2696E

Date of Loss: 16/03/2020 Nature of Claim: TP Claim No: 4872542927SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGY7740L</b>	Engine No:	CVK067329
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF4XJA219763
Reg. Date:	31/10/2018 (Man. Year: 2018)	Odometer:	25107 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,247.00	3,232.32	14,014.68	81.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,222.00	2,900.00	56.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>22,369.00</b>	<b>5,454.32</b>	<b>16,914.68</b>	<b>75.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,565.83	381.80	1,184.03	75.62
<b>Nett Amount (S\$)</b>	<b>23,934.83</b>	<b>5,836.12</b>	<b>18,098.71</b>	<b>75.62</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,138.12</b>		

### INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,068.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	185.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cut	1,254.00 FS	*1,003.20 FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	254.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS
10	1		*FRONT BUMPER COVER	Not Necessary	120.00 FS	*- FS
11	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
12	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	54.00 FS	*- FS
15	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
16	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
17	2		*BONNET LID HINGE-LH/RH	Not Necessary	574.00 FS	*- FS
18	1		*BONNET IMPACT PROTECTION-CENTRE	Necessary	26.00 FS	*20.80 FS
19	2		*BONNET IMPACT PROTECTION-LH/RH	Necessary	52.00 FS	*41.12 FS
20	2		*BONNET STRIKER-LH/RH	Not Necessary	94.00 FS	*- FS
21	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
22	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	54.00 FS	*- FS
23	1		*BONNET RELEASE CABLE	Not Necessary	54.00 FS	*- FS
24	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
25	1		*LED HEADLIGHT-LH/RH	Not Necessary	7,321.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	15.00 FS	*- FS
27	1		*RADIATOR AIR GUIDE-LH	Not Necessary	27.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE-LH	Not Necessary	12.00 FS	*- FS
29	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
30	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>17,247.00</b>
						<b>3,232.32</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,122.00</b>	<b>2,222.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >