

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004158/R1DA3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800106554

Claimant
Vehicle No : SMA4799T **Insured Vehicle No :** SFR8910E

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 6581011293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4799T		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ940477
Reg. Date:	09/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V7J1066524
Colour:	Blue	Odometer:	45910 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,048.40	8,135.20	17,913.20	68.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,722.00	7,022.00	7,700.00	52.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	40,770.40	15,157.20	25,613.20	62.82
+ GST 7.00/7.00% (S\$)	2,853.93	1,061.00	1,792.93	62.82
Nett Amount (S\$)	43,624.33	16,218.20	27,406.13	62.82
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		17,220.20		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020 Inspected At: 24 Benoi Sector
Repairer: Premium Automobiles Pte Ltd (HQ)

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,894.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	36.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	151.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	505.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	280.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM -LH	Not Necessary	153.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ADAPTER -LH	Not Necessary	36.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Necessary	180.00 FS	*143.60 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	177.00 FS	*- FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Necessary	681.00 FS	*544.80 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Necessary	178.00 FS	*142.40 FS
14	1		*FOAM FILLER PIECE COVER	Necessary	115.00 FS	*91.60 FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
17	1		*SIGNAL HORN- LH HIGH TONE	Not Necessary	188.00 FS	*- FS
18	1		*BONNET	Not Necessary	2,988.00 FS	*- FS
19	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
20	1		*BONNET EDGE PROTECTION	Not Necessary	26.00 FS	*- FS
21	1		*BONNET CATCH HOOK	Not Necessary	60.00 FS	*- FS
22	1		*LED HEADLIGHT -LH/RH	Not Necessary	5,193.00 FS	*- FS
23	1		*LIFT CYLINDER -LH	Not Necessary	134.00 FS	*- FS
24	1		*RADIATOR AIR GUIDE -LH	Necessary	23.00 FS	*18.46 FS
25	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	12.00 FS	*- FS
26	1		*REAR BUMPER	Deformed	1,851.00 FS	*1,480.80 FS
27	4		*REAR BUMPER STICKY PAD	Not Necessary	22.00 FS	*- FS
28	1		*REAR BUMPER FIXING PARTS	Not Necessary	182.00 FS	*- FS
29	2		*WHEEL HOUSING LINER ADAPTER -LH/RH	Not Necessary	72.00 FS	*- FS
30	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	30.00 FS	*- FS
31	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	55.00 FS	*- FS
32	1		*REAR BUMPER SPOILER	Scratched	223.00 FS	*178.40 FS
33	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	78.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	538.00 FS	*- FS
35	1		*REAR BUMPER BRACKET -LH	Not Necessary	26.00 FS	*- FS
36	1		*REAR BUMPER BRACKET -LH	Not Necessary	27.00 FS	*- FS
37	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	124.00 FS	*- FS
38	2		*REAR PARKING SENSOR -INNER /OUTER	Necessary	392.80 FS	*392.80 FS
39	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
40	1		*REAR LID	Bent	2,444.00 FS	*1,955.20 FS
41	1		*REAR LID ATTACHMENT PARTS	Not Necessary	278.00 FS	*- FS
42	2		*REAR LID HINGE -LH/RH	Not Necessary	482.00 FS	*- FS
43	1		*REAR LID FLAP GASKET	Not Necessary	193.00 FS	*- FS
44	1		*REAR LID LOCK STRIKER	Not Necessary	47.00 FS	*- FS
45	1		*REAR LID LOCK STRIKER	Not Necessary	182.00 FS	*- FS
46	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.24 FS
47	1		*AUDI EMBLEM	Necessary	117.00 FS	*93.20 FS
48	1		*A3 INSCRIPTION	Necessary	90.00 FS	*71.76 FS
49	1		*TFSI INSCRIPTION	Necessary	90.00 FS	*71.76 FS
50	1		*REAR CROSS PANEL	Necessary	339.00 FS	*270.80 FS
51	1		*CROSS PANEL REINFORCEMENT	Repair	691.00 FS	*- FS
52	1		*REAR CROSS PANEL CONNECTING PLATE -LH	Not Necessary	136.00 FS	*- FS
53	1		*REAR CROSS PANEL TRIM	Not Necessary	146.00 FS	*- FS
54	1		*REAR SILENCER	Bent	677.00 FS	*541.60 FS
55	1		*REAR SILENCER DUAL CLIP	Necessary	55.00 FS	*43.60 FS
56	2		*EXHAUST SYSTEM RETAINER	Not Necessary	77.00 FS	*- FS
57	1		*REAR SILENCER HEAT SHIELD	Not Necessary	157.00 FS	*- FS
58	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
59	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
60	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
61	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
62	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
63	1		*SUNDRIES	Necessary	500.00 FS	*58.58 FS
64	1		*CENTRE EXHAUST SILENCER	Necessary	375.60 FS	*375.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **26,048.40** **8,135.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
5	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY	New	480.00	480.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO CUT OUT AND WELD END PANELLING .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,200.00	2,250.00
8	TO RESPRAY REAR BUMPER ,REAR LID ,HINGES ,REAR END PANELLING AND SPARE WHEEL HOUSING	New	4,000.00	1,650.00
9	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	480.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,722.00	7,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >