

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20004163/AGSF3E2
Date: 08/09/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/20-408804
Claimant Vehicle No :	SGT2423L	Insured Vehicle No :	FBF8856P
Date of Loss:	13/03/2020	Nature of Claim:	TP
		Claim No:	MSC/V/20-000392

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT2423L	Engine No:	HR15101498A
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0004433
Reg. Date:	04/04/2007 (Man. Year: 2007)	Odometer:	187879 km
Colour:	Brown		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,519.32	1,587.80	4,931.52	75.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,650.00	1,630.00	49.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,799.32	3,237.80	6,561.52	66.96
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	9,799.32	2,600.00	7,199.32	73.47

INSPECTION

Date of Assignment:	17/03/2020	
Date Inspected:	18/03/2020	Inspected At:
		Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2020)
Parts: 143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGT2423L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,125.20 FL	*- FL
2	1		*REAR BOOTLID LATIO EMBLEM	Necessary	71.00 FL	*71.00 FL
3	1		*REAR BOOTLID LOGO	Necessary	69.00 FL	*69.00 FL
4	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	211.00 FL	*- FL
5	1		*REAR BOOTLID LOCK	Not Necessary	195.20 FL	*- FL
6	1		*REAR BUMPER	Deformed	896.80 FL	*475.00 FL
7	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	231.00 FL	*90.00 FL
8	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	211.00 FL	*- FL
9	1		*REAR BUMPER ANTENNA KEYLESS	Cracked	225.00 FL	*75.00 FL
10	1		*REAR END PANEL	Dented	755.20 FL	*442.70 FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	263.80 FL	*- FL
12	1		*REAR TAILLAMP LH & RH	N/S Cracked	1,221.40 FL	*219.30 FL
13	1		*REAR TAILLAMP PANEL LH	Not Necessary	379.20 FL	*- FL
14	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
15	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
16	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
17	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
18	1		*REVERSE CAMERA	Not Necessary	430.00 FS	*- FS
19	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	120.00 FS	*- FS
21	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,104.80	1,732.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	585.48	144.20
Total Parts (\$\$)	6,519.32	1,587.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	650.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	750.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	80.00
5	TO REMOVE / REFIX UPHOLSTERY	New	150.00	80.00
6	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
7	TO REMOVE REVERSE SENSORS	New	100.00	60.00
			Gross Labour Cost (S\$)	1,650.00
			3,280.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >