



Your Ref : 6541913643SG

Date: 15th April 2020

Our Ref : CS/AIG20004176/Eyd3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GV 657G
INSURED VEHICLE GW 5402L ACCIDENT ON 06/03/2020**

Instruction was received to inspect the vehicle Reg. No. GV 657G. The inspection was conducted on 18/03/2020 at the premises of M/s My Car Consultant Pte Ltd, 53 Ubi Avenue 1 #01-33, Paya Ubi Industrial Park, Singapore 408934.

The following vehicle information was recorded:

Registration Number	: GV 657G
Make/Model	: Mitsubishi L300 P/VAN
Year of Registration	: 2001
Body Colour	: Beige
Chassis Number	: JMAJNP15VYA001512
Engine Capacity	: 2477 cc
Speedometer Reading	: 385265 km

The vehicle sustained damages at the front o/s portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 6,500.00
Less: LTA Reimbursement Value (RV)	(S\$ 5,252.00)
Nett Liability	<u>S\$ 1,248.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.