

成 耀 摩 哆 廠

## SENG YEOW MOTOR WORKS

Blk 14 Defu Lane 10, #01-404, Industrial Park D (Hougang), Singapore 539195

Tel: 6288 6184 Fax: 6286 7298 H/Phone: 9756 5147

Business Registration No.: 44383700K

23 Nov 2019

LIAO PING  
C/O BLK 14 #01-404  
DEFU LANE 10  
SINGAPORE 539195

ATTENTION: MOTOR CLAIM DEPARTMENT

RE: FINAL BILL FOR HYUNDAI AVANTE VEHICLE NO: SJS 3518K

YOUR INSURED VEHICLE NO: SLV 582D

ACCIDENT DATE: 09 NOVEMBER 2019

To Repair the above caption vehicle on a Lump Sum basis include Replacement of Spare Part, Spray Painting and Labour Charge.

Lump Sum \$6,700.00

Survey Report Fee: \$586.00

成 耀 摩 哆 廠  
SENG YEOW MOTOR WORKS

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

## INVOICE

Liao Ping  
C/o: Seng Yeow Motor Works  
Blk 14 Defu Lane 10 #01-404  
Singapore 539195

Invoice No: CL/191390

Ref No: SYM/11/1901/TP

Date: 20 November 2019

DESCRIPTION	AMOUNT
<b>OUR SERVICE FEE CHARGES:</b>	
• SURVEY INSPECTION FOR VEHICLE NO. <u>SJS 3518 K</u>	
• RESURVEY INSPECTION	
• DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)	
• TRANSPORTATION	
<b>GRAND TOTAL</b>	<b>S\$ 586.00</b>

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Liao Ping  
C/o: Seng Yeow Motor Works  
Blk 14 Defu Lane 10 #01-404  
Singapore 539195

Date : 20 November 2019  
Our ref : SYM/11/1901/TP

Accident Date : 09 November 2019  
Inspection Date : 11 November 2019  
Repairer Name : Seng Yeow Motor Works  
Blk 14 Defu Lane 10 #01-404  
Singapore 539195

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SJS 3518 K  
Make / Model : Hyundai Avante  
Chassis No : KMH DU41BR9U802913  
Engine No : G4FC9U681082

Year / Capacity : 2009 / 1591 cc  
Colour : Silver  
Mileage : 124962

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Westlake	185/65 R15	5 mm	Sport
Front Offside	: Westlake	185/65 R15	5 mm	Sport
Rear Nearside	: Westlake	185/65 R15	5 mm	Sport
Rear Offside	: Westlake	185/65 R15	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 66 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle  
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,700.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: SJS 3518 K

Our Ref No: SYM/11/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear windscreen moulding	Necessary	\$ 89.60	\$ 89.60
1	Rear bumper	Damage	\$ 486.90	\$ 486.90
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00
1	Rear bumper side retainer	Necessary	\$ 44.80	\$ 44.80
1	Rear o/s fender	Damage	\$ 1,703.00	\$ 1,703.00
1	Rear o/s wheel hub c/w bearing	Damage	\$ 317.60	\$ 317.60
1	Rear o/s shock absorber	Damage	\$ 286.50	\$ 286.50
1	Rear o/s knuckle arm	Damage	\$ 481.60	\$ 481.60
1	Rear o/s lower arm	Damage	\$ 315.00	\$ 315.00
1	Rear o/s stay arm	Damage	\$ 189.00	\$ 189.00
1	Rear o/s trailing arm	Damage	\$ 385.00	\$ 385.00
1	Rear o/s door	Damage	\$ 1,106.20	\$ 1,106.20
1	Rear o/s door outer handle	Damage	\$ 110.80	\$ 110.80
1	Rear o/s door weather strip	Necessary	\$ 126.20	\$ 126.20
			<b>\$ 5,692.20</b>	<b>\$ 5,692.20</b>
			<i>Less 20%</i>	<i>\$ 1,138.44</i>
<b>Total Cost - List Items</b>			<b>\$ 4,553.76</b>	<b>\$ 4,553.76</b>

## SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00
1	Rear o/s tyre (Depreciation)	Damage	\$ 400.00	\$ 200.00
1	Rear o/s wheel rim	Damage	\$ 750.00	\$ 750.00
<b>Total Cost - Special Nett items</b>			<b>\$ 1,230.00</b>	<b>\$ 1,000.00</b>

**Total cost of parts**

<b>\$ 5,783.76</b>	<b>\$ 5,553.76</b>
--------------------	--------------------

Vehicle Registration No: SJS 3518 K

Our Ref No: SYM/11/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 5,783.76</b>	<b>\$ 5,553.76</b>

## **LABOUR**

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00
3	To remove and refit rear undercarriage.	\$ 350.00	\$ 300.00
4	To conduct wheel alignment.	\$ 150.00	\$ 120.00
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00
6	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 150.00	\$ 120.00
7	To apply undercoating on repaired and replaced panel.	\$ 120.00	\$ 90.00
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00	\$ 1,000.00
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00

**GRAND TOTAL**

**\$ 9,563.76    \$ 8,353.76**

Vehicle Registration No: SJS 3518 K

Our Ref No: SYM/11/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,700.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**

  
\_\_\_\_\_  
Cheong K. H.  
Automotive Appraiser





APPRaiser PTE LTD



