

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20004185/ABS3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100383446

Claimant
Vehicle No : GBH4529A **Insured Vehicle No :** GBD3115M

Date of Loss: 16/03/2020 Nature of Claim: TP Claim No: 3758269957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4529A		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2806213
Reg. Date:	08/06/2018 (Man. Year: 2018)	Chassis No:	JTFHT02P500243072
Colour:	Silver	Odometer:	58972 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,862.60	3,943.55	10,919.05	73.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,070.00	1,630.00	44.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,562.60	6,013.55	12,549.05	67.60
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	18,562.60	4,800.00	13,762.60	74.14
+ Loss of Use (7.0 x S\$70.00/day) (\$\$)		490.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,292.00		

INSPECTION

Date of Assignment: 17/03/2020

Date Inspected: 17/03/2020 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6,
#01-43
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
2	1		*REAR BOOT LID	Dented	1,712.45 F	*1,712.45 FL
3	2		*REAR BOOT LID HINGE	Not Necessary	343.40 F	*- FL
4	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	749.30 F	*- FL
5	1		*REAR BOOT LID EMBLEM LOGO	Necessary	41.20 F	*41.20 FL
6	1		*REAR BOOT LID TOYOTA STICKER	Necessary	57.50 F	*57.50 FL
7	1		*REAR BOOT LID HIACE STICKER	Necessary	63.90 F	*63.90 FL
8	1		*REAR BOOT LID 70KM/H STICKER	Necessary	20.00 F	*20.00 FL
9	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	281.90 F	*- FL
10	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
11	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	126.20 F	*- FL
12	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	680.00 F	*- FL
13	1		*REAR BOOT LID TRIMBOARD	Not Necessary	581.10 F	*- FL
14	8		*REAR BOOT LID TRIMBOARD CLIP	Not Necessary	52.00 F	*- FL
15	1		*REAR BOOT LID LOCK	Damaged	374.20 F	*374.20 FL
16	1		*REAR BOOT LID WEATHERSTRIP	Cut	381.90 F	*381.90 FL
17	1		*REAR TAIL LAMP	N/S Cracked	748.90 F	*374.45 FL
18	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*10.00 FL
19	1		*REAR TAIL LAMP LOWER COVER	O/S Deformed	371.85 F	*85.00 FL
20	2		*REAR TAIL LAMP LOWER COVER RETAINER	Not Necessary	342.90 F	*- FL
21	2		*REAR TAIL LAMP PANEL	Repair	743.70 F	*- FL
22	1		*REAR BUMPER	Deformed	374.45 F	*374.45 FL
23	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
24	2		*REAR BUMPER SIDE RETAINER	Necessary	262.70 F	*262.70 FL
25	1		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*REAR END PANEL OUTER	Dented	581.10 F	*581.10 FL
27	1		*REAR END PANEL INNER	Repair	591.25 F	*- FL
28	1		*REAR END PANEL TOP GARNISH	Bent	274.45 F	*274.45 FL
29	1		*REAR EXHAUST	Not Necessary	1,712.85 F	*- FL
30	2		*REAR EXHAUST MOUNTING	Not Necessary	122.20 F	*- FL
31	1		*REAR CENTER EXHAUST	Not Necessary	1,829.10 F	*- FL
32	1		*PLYWOOD	Not Necessary	680.00 F	*- FL
33	1		*REAR SPARE TYRE BRACKET	Bent	243.10 F	*243.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,862.60 5,191.40
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,247.85

Total Parts (\$\$) 14,862.60 3,943.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	120.00
4	GUM	New	60.00	60.00
5	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	0.00
6	TO CHECK WIRING	New	100.00	30.00
7	TOWING FEE	New	150.00	0.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	1,200.00	850.00
10	SPRAY PAINTING	New	1,200.00	850.00
Gross Labour Cost (\$\$)			3,700.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >