

SM AUTOMOTIVE

AIG.

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

CC6 / ALG 2000 4185 / Ah S3

16-03-2020

01-43

TP AIG

Singapore 417883

Vic

Accident date: 16/03/2020

Estimated repair cost for vehicle no: GBH4529A TOYOTA HIACE VAN 3.0 M '18

CHASSIS: JTFHT02P500243072

S/n	Qty	Items	U/price	Amount	
1	1	Rear Windscreen Seal <i>Neu</i>		\$105.00	✓
2	1	Rear Boot Lid <i>Dented</i>		\$1,712.45	✓
3	2	Rear Boot Lid Hinge	\$171.70	\$343.40	+
4	2	Rear Boot Lid Shock Absorber <i>2 not Neu</i>	\$374.65	\$749.30	+
5	1	Rear Boot Lid Emblem Logo		\$41.20	—
6	1	Rear Boot Lid Toyota Sticker <i>Neu</i>		\$57.50	—
7	1	Rear Boot Lid Hiace Sticker		\$63.90	—
8	1	Rear Boot Lid 70km/H Sticker		\$20.00	✓
9	1	Rear Boot Lid Center Moulding		\$281.90	+
10	1	Rear Boot Lid Number Plate		\$50.00	+
11	2	Rear Boot Lid Number Plate Lamp <i>1 not Neu</i>	\$63.10	\$126.20	+
12	1	Rear Boot Lid Reverse Camera		\$680.00	+
13	1	Rear Boot Lid Trimboard		\$581.10	+
14	8	Rear Boot Lid Trimboard Clip <i>2 not Neu</i>	\$6.50	\$52.00	+
15	1	Rear Boot Lid Lock <i>Dented</i>		\$374.20	✓
16	1	Rear Boot Lid Weatherstrip <i>Cut</i>		\$381.90	✓
17	2	Rear Tail Lamp <i>RH could</i>	\$374.45	\$748.90	→ 374.45
18	4	Rear Tail Lamp Clip <i>Neu</i>	\$8.00	\$32.00	→ 10
19	2	Rear Tail Lamp Lower Cover <i>RH Dented</i>		\$371.85	85
20	2	Rear Tail Lamp Lower Cover Retainer <i>Neu</i>	\$171.45	\$342.90	+
21	2	Rear Tail Lamp Panel <i>Repair</i>	\$371.85	\$743.70	+
22	1	Rear Bumper <i>Dented</i>		\$374.45	✓
23	8	Rear Bumper Clip <i>Neu</i>	\$6.50	\$52.00	30
24	2	Rear Bumper Side Retainer <i>Neu</i>	\$131.35	\$262.70	—
25	1	Rear Bumper Reverse Sensor <i>Dented</i>		\$280.00	200/SW
26	1	Rear End Panel Outer <i>Dented</i>		\$581.10	2
27	1	Rear End Panel Inner <i>Repair</i>		\$591.25	+
28	1	Rear End Panel Top Garnish <i>Neu Best</i>		\$274.45	✓
29	1	Rear Exhaust <i>Neu Neu</i>		\$1,712.85	+

30	2	Rear Exhaust Mounting	2	\$61.10	\$122.20 +
31	1	Rear Center Exhaust	14		\$1,829.10 +
32	1	Plywood			\$680.00 +

474830

356122

S.N: 220

Subtotal :- \$14,619.50

Labour charges

To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 50
To remove & refit rear windscreen	\$180.00 120
Gum	\$60.00 ✓
To remove & refit rear & center exhaust	\$380.00 +
To check wiring	\$100.00 30
Towing fee	\$150.00 +
Tuff kote	\$150.00 60
Panel beating	\$1,200.00 850
Spray painting	\$1,200.00 850

Subtotal :- \$3,700.00

Total :- \$18,319.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:-

Adrian L
2/S 17/03/20
06 Days.

Supplementary: 182.32

Total: 6013.54

4/S: 481C. ✓

(A81C)

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

17/03/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 16/03/2020

Supplementary repair cost for veh no: GBH4529A TOYOTA HIACE VAN 3.0 M '18

S/n	Qty	Items	U/price	Amount
1	1	Rear Spare Tyre Bracket <i>Bent</i>		\$243.10 ✓

Total:- \$243.10

Adrian S
17/03/20

243.10

182.32