

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III20004186/KGA3Q2

**Date:** 30/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHB7822T	<b>Insured Vehicle No :</b>	SHC3511L
Date of Loss: 14/03/2020	Nature of Claim: TP	Claim No: MCT20030234

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB7822T</b>	Engine No:	2ZR2C52930
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU103083452
Reg. Date:	30/08/2019 (Man. Year: 2018)	Odometer:	53293 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 2 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 2 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,490.45	2,533.87	8,956.58	77.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,000.00	760.00	13,240.00	94.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,490.45</b>	<b>3,293.87</b>	<b>22,196.58</b>	<b>87.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,784.33</b>	<b>230.57</b>	<b>1,553.76</b>	<b>87.08</b>
<b>Nett Amount (S\$)</b>	<b>27,274.78</b>	<b>3,524.44</b>	<b>23,750.34</b>	<b>87.08</b>
<b>+ Loss of Use (3.0 x S\$40.00/day) (S\$)</b>		120.00		
<b>+ Car Rental (3.0 x S\$96.30/day) (S\$)</b>		288.90		
<b>Nett Liability (S\$)</b>		<b>3,933.34</b>		

#### INSPECTION

Date of Assignment:	17/03/2020	
Date Inspected:	17/03/2020 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2020)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB7822T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	516.00 FL	*516.00 FL
2	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	103.40 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	80.10 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	82.30 FL	*82.30 FL
5	1		*REINFORCEMENT ,FRONT BUMPER	Repair	716.60 FL	*- FL
6	1		*REINFORCEMENT ,FRONT BUMPER NO,2	Serviceable	246.10 FL	*- FL
7	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
8	1		*ABSORBER ,FRONT BUMPER LOWER	Serviceable	132.70 FL	*- FL
9	1		*COVER SUB-ASSY ,ENGINE UNDER ,NO,2	Serviceable	241.90 FL	*- FL
10	1		*COVER SUB-ASSY ,ENGINE ,NO.1	Serviceable	472.40 FL	*- FL
11	1		*COVER ,FRONT BUMPER HOLE ,LH	Serviceable	29.30 FL	*- FL
12	1		*EXTENSION ,FRONT BUMPER ,LH	Serviceable	120.10 FL	*- FL
13	1		*FRONT LED LAMP (LOWER) LH	Serviceable	951.40 FL	*- FL
14	1		*FRONT HEADLAMP LH	Cracked	2,637.60 FL	*2,637.60 FL
15	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	960.50 FL	*- FL
16	1		*MOTOR ,HEADLAMP LEVELING ,LH	Serviceable	487.50 FL	*- FL
17	1		*FRONT FENDER LH	Repair	977.80 FL	*- FL
18	1		*LINER ,FRONT FENDER ,LH	Serviceable	202.50 FL	*- FL
19	1		*FRONT FENDER EMBLEM LH	Necessary	54.60 FL	*54.60 FL
20	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
21	1		*GRILLE RADIATOR ,LOWER NO.1	Serviceable	170.10 FL	*- FL
22	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
23	1		*FRONT BONNET	Repair	983.10 FL	*- FL
24	1		*HINGE ASSY ,HOOD ,LH	Repair	58.90 FL	*- FL
25	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Serviceable	594.80 FL	*- FL
26	1		*COVER ,RADIATOR SUPPORT OPENING	Serviceable	235.30 FL	*- FL
27	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	*- FS
28	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
29	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
30	1		*CLIP, FRONT FENDER LINER	Not Necessary	35.00 FS	*- FS
31	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
32	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
33	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
34	1		*SET ROCKER PANEL MOULDING CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,383.30</b>	<b>3,356.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,892.85	822.63
<b>Total Parts (\$\$)</b>	<b>11,490.45</b>	<b>2,533.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	300.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALACING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
11	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,000.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >