

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/FWD20004190/APS3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00003458-01
Claimant Vehicle No :	SJH8315D	Insured Vehicle No :	SLB6250C
Date of Loss:	16/03/2020	Nature of Claim:	TP
			Claim No: 1202000014174

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH8315D		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ3126994
Reg. Date:	26/08/2008 (Man. Year: 2008)	Chassis No:	JTDER12WX03000573
Colour:	White	Odometer:	179815 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	RADAR 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RADAR 6 mm	Rear Right Side:	RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,316.45	3,169.65	1,146.80	26.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,430.00	970.00	40.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,716.45	4,599.65	2,116.80	31.52
Approved Total (Overridden) (S\$)		3,600.00		

(S\$)	6,716.45	3,600.00	3,116.45	46.40
+ GST 7.00/7.00% (S\$)	470.15	252.00	218.15	46.40
Nett Amount (S\$)	7,186.60	3,852.00	3,334.60	46.40
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		4,559.45		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 17/03/2020

Date Inspected: 18/03/2020

Inspected At:

TWINCAR AUTOMOTIVE PTE LTD
 2 KAKI BUKIT AVE 2
 #01-17 KAKI BUKIT AUTOHUB
 SINGAPORE 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH8315D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,277.10 FL	*1,277.10 FL
2	2		*REAR BUMPER BRACKET L/R	Not Necessary	264.40 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	262.70 FL	*262.70 FL
4	1		*REAR END LOWER PANEL	Dented	241.85 FL	*241.85 FL
5	1		*REAR END PANEL	Dented	689.75 FL	*689.75 FL
6	1		*REAR END PANEL INNER TOP GARNISH	Deformed	374.55 FL	*374.55 FL
7	1		*REAR TAILGATE LOGO EMBLEM	Necessary	132.25 FL	*132.25 FL
8	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	191.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	182.10 FL	*- FL
10	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Not Necessary	85.50 FL	*- FL
11	2		*REAR TAILLAMP L/R	Cracked	1,262.60 FL	*818.00 FL
12	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	244.20 FL	*110.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
14	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
15	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
16	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
17	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,618.60	4,146.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,302.15	976.55
Total Parts (\$\$)	4,316.45	3,169.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	50.00	50.00
2	TO REMOVE REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	30.00
3	TO RESPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,200.00	700.00
4	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	50.00
Gross Labour Cost (S\$)			2,400.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >