

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20004199/UGA3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJK8420S	Insured Vehicle No :	SHA3875Y
Date of Loss: 16/03/2020	Nature of Claim: TP	Claim No: MCT20030268

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8420S		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4100249
Reg. Date:	05/11/2008 (Man. Year: 2008)	Chassis No:	GE61090780
Colour:	Black	Odometer:	146421 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,300.24	3,765.52	10,534.72	73.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,380.00	1,890.00	44.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,570.24	6,145.52	12,424.72	66.91
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	18,570.24	4,900.00	13,670.24	73.61

INSPECTION

Date of Assignment:	17/03/2020	
Date Inspected:	18/03/2020 Inspected At:	15 KAKI BUKIT ROAD # 01-53
		Repairer: Zoom Autowerks Pte Ltd (Bedok)
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8420S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (GRAZED)	Not Consistent With The Impact	580.50 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	48.10 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	354.50 FL	*- FL
4	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	214.30 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
6	1		*FRONT FENDER LH	Dented / Bent	496.60 FL	*386.60 FL
7	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	194.30 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
9	1		*FRONT FENDER QUARTER GLASS C/W MOULDING LH	Not Necessary	79.20 FL	*- FL
10	1		*FRONT FENDER LAMP LH	Not Necessary	68.40 FL	*- FL
11	1		*FRONT HEADLAMP LH	Not Necessary	1,159.00 FL	*- FL
12	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	93.40 FL	*- FL
13	1		*FRONT SUSPENSION LH	Serviceable	438.00 FL	*- FL
14	1		*FRONT KNUCKLE ARM LH	Bent	479.00 FL	*355.20 FL
15	1		*FRONT KNUCKLE HUB LH	Bent	214.70 FL	*214.70 FL
16	1		*FRONT HUB BEARING	Necessary	162.20 FL	*145.80 FL
17	1		*FRONT SUSPENSION LINKAGE LH	Not Necessary	101.10 FL	*- FL
18	1		*FRONT LOWER ARM LH	Not Necessary	427.90 FL	*- FL
19	1		*FRONT ABS SENSOR LH	Not Necessary	246.80 FL	*- FL
20	1		*FRONT DOOR LH	Dented / Bent	1,210.30 FL	*781.90 FL
21	1		*FRONT DOOR HINGE TOP LH	Not Necessary	109.80 FL	*- FL
22	1		*FRONT DOOR HINGE LOWER LH	Not Necessary	106.70 FL	*- FL
23	1		*FRONT DOOR INNER TRIMBOARD LH	Deformed / Cracked	797.40 FL	*366.10 FL
24	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*45.00 FL
25	1		*FRONT DOOR POWER WINDOW REGULATOR N/S	Bent	246.70 FL	*246.70 FL
26	1		*FRONT DOOR POWER WINDOW MOTOR LH	Shorted / Jammed	467.90 FL	*355.20 FL
27	1		*FRONT DOOR INNER LOCK ASSY LH	Not Necessary	394.10 FL	*- FL
28	1		*FRONT DOOR WEATHER STRIP LH	Necessary	149.80 FL	*98.50 FL
29	1		*FRONT DOOR PILLAR OUTER LH	Repair	946.80 FL	*- FL
30	1		*WING MIRROR MOTOR ASSY LH	Not Necessary	694.40 FL	*- FL
31	1		*CENTRE DOOR PILLAR OUTER LH	Repair	926.80 FL	*- FL
32	1		*REAR DOOR LH	Dented / Bent	1,440.50 FL	*755.20 FL
33	1		*REAR DOOR HINGE TOP LH	Not Necessary	117.20 FL	*- FL
34	1		*REAR DOOR HINGE LOWER LH	Not Necessary	114.40 FL	*- FL
35	1		*REAR DOOR INNER TRIMBOARD LH	Not Necessary	784.40 FL	*- FL
36	1		*REAR DOOR INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
37	1		*REAR DOOR POWER WINDOW LINKAGE LH	Not Necessary	231.40 FL	*- FL
38	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	463.50 FL	*- FL
39	1		*REAR DOOR INNER LOCK ASSY LH	Not Necessary	342.20 FL	*- FL
40	1		*REAR DOOR WEATHER STRIP LH	Necessary	178.00 FL	*98.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*ROCKER PANEL LH	Badly Dented	382.50 FL	*382.50 FL
42	1		*ROCKER GARNISH CLIPS	No such part	60.00 FL	*- FL
43	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
44	1		*BRAKE OIL	Not Necessary	80.00 FS	*- FS
45	1		*FRONT DOOR VISOR N/S	Necessary	150.00 FS	*40.00 FS
46	1		*REAR DOOR VISOR N/S	Necessary	150.00 FS	*40.00 FS
47	1		*FRONT SPORT RIM LH	Cut	550.00 FS	*300.00 FS
48	1		*REAR SPORT RIM LH	Repair	550.00 FS	*- FS
49	1		*FRONT TYRE LH	Serviceable	210.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,452.80 4,611.90
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,152.56 846.38

Total Parts (\$\$) 14,300.24 3,765.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,600.00	1,080.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
5	TO RENEW ,BALANCE & REPLACE FRONT LH TYRE	New	80.00	0.00
6	TO REMOVE & INSTALL FRONT DOOR COMPONENT LH	New	180.00	60.00
7	TO REMOVE & INSTALL REAR DOOR COMPONENT LH	New	180.00	60.00
8	TO REMOVE & INSTALL REAR FENDER INTERIOR GARNISH ,SEAT ,CARPETS TO FACILITATE REPAIRS	New	200.00	80.00
9	TO REMOVE & INSTALL FRONT LH UNDERCARRIAGE	New	250.00	120.00
10	TO RUST PROOF AFFECTED AREAS	New	150.00	100.00
Gross Labour Cost (\$\$)			4,270.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >