

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20004201/T1BA3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800082455
Claimant
Vehicle No : SLR2282C **Insured Vehicle No :** SKR4845C
Date of Loss: 14/03/2020 **Nature of Claim:** TP **Claim No:** 0788510181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR2282C**
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8149120
 Reg. Date: 03/08/2017 (Man. Year: 2017) Chassis No: ZYX102056249
 Colour: Green Odometer: 245482 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,821.62	5,011.35	1,810.27	26.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,990.00	1,110.00	35.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,921.62	7,001.35	2,920.27	29.43
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	9,921.62	5,600.00	4,321.62	43.56
+ GST 7.00/7.00% (S\$)	694.51	392.00	302.51	43.56
Nett Amount (S\$)	10,616.13	5,992.00	4,624.13	43.56
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,728.45		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment: 17/03/2020
 Date Inspected: 17/03/2020 Inspected At: Em-1 Auto Pte Ltd (HQ)
 Blk 8 Sin Ming Industrial Estate Sector C, #01-68
 Singapore 575643
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,260.10 FL	*1,260.10 FL
2	1		*TAILGATE EMBLEM BADGE	Necessary	62.70 FL	*62.70 FL
3	1		*TAILGATE EMBLEM HYBRID	Necessary	59.10 FL	*59.10 FL
4	1		*TAILGATE EMBLEM CHR	Necessary	59.10 FL	*59.10 FL
5	1		*TAILGATE LAMP LH	Not Necessary	298.50 FL	*- FL
6	1		*TAILGATE LAMP SEALER	Not Necessary	38.00 FL	*- FL
7	1		*SET TAILGATE LAMP CLIPS	Not Necessary	25.00 FL	*- FL
8	1		*SET TAILGATE INNER TRIMS CLIPS	Not Necessary	40.00 FL	*- FL
9	1		*TAILGATE INNER LOCK	Bent	448.30 FL	*373.00 FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	56.20 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	321.70 FL	*321.70 FL
12	1		*REAR BUMPER	Deformed	916.40 FL	*916.40 FL
13	1		*REAR BUMPER LOWER SKIRT	Cut	592.70 FL	*397.60 FL
14	1		*REAR BUMPER SIDE RETAINER	O/S Not Necessary /N/SDeformed	144.20 FL	*72.10 FL
15	1		*REAR BUMPER ATTACHMENT RETAINER	O/S Not Necessary /N/SDeformed	112.00 FL	*56.00 FL
16	1		*SET REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
17	1		*REAR BUMPER REFLECTOR LH	Not Necessary	56.20 FL	*- FL
18	1		*REAR BUMPER REFLECTOR COVER LH	Cut	92.70 FL	*92.70 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	451.70 FL	*451.70 FL
20	1		*TAILLAMP LH	Not Necessary	521.80 FL	*- FL
21	1		*TAILLAMP INNER SEALER	Not Necessary	38.00 FL	*- FL
22	1		*SET TAILLAMP CLIPS	Not Necessary	25.00 FL	*- FL
23	1		*END PANEL	Bent	724.10 FL	*724.10 FL
24	1		*END PANEL TOP TRIM	Deformed	327.10 FL	*266.60 FL
25	1		*SET END PANEL TOP TRIM CLIP	Necessary	30.00 FL	*30.00 FL
26	1		*REAR KEY ANTENA	Cracked	116.40 FL	*116.40 FL
27	1		*REAR FENDER WHEEL ARCH PROTECTOR LH	Deformed	237.10 FL	*237.10 FL
28	1		*REAR EXHAUST SILENCER	Dented	593.00 FL	*593.00 FL
29	2		*REAR EXHAUST MOUNTINGS	Not Necessary	76.00 FL	*- FL
30	1		*REAR EXHAUST GASKET	Necessary	46.20 FL	*46.20 FL
31	1		*REAR EXHAUST HEAT PIPE	Bent	126.20 FL	*126.20 FL
32	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
33	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
34	1		*REAR NUMBER PLATE WITH HOLDER	Cut	50.00 FS	*45.00 FS
35	1		*SET REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,805.50	6,586.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,983.88	1,575.45
Total Parts (\$\$)	6,821.62	5,011.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	90.00	30.00
5	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
6	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
8	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
9	REMOVE AND INSTALL REAR CAMERA	New	120.00	60.00
Gross Labour Cost (\$)			3,100.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >